2002 ENGINES 3.5L V6 - Sedona

2002 ENGINES

3.5L V6 - Sedona

GENERAL

SPECIFICATIONS

| Description | Specification | Limit |
|---------------------------------------|-----------------------------------|-------|
| Description | 3.5 | 1 |
| General | | |
| Туре | DOHC V-type | |
| Number of cylinders | 6 | |
| Bore | 93 mm (3.66 in) | |
| Stroke | 85.8 mm (3.38 in) | |
| Total displacement | 3497 cc (213.3 cu.in) | |
| Compression ratio | 10.0 | |
| Firing order | 1-2-3-4-5-6 | |
| Idle R.P.M | 700±100 | |
| Ignition timing at idling speed | BTDC 10°±2° | |
| Valve timing | | |
| Intake valve | | |
| Opens (BTDC) | 11.5° | |
| Closes (ABDC) | 60.5° | |
| Exhaust valve | | |
| Opens (BBDC) | 43.5° | |
| Closes (ATDC) | 20.5° | |
| Camshaft | | |
| Cam height (mm) | | |
| Intake | 35.098 ~ 35.298 (1.38 - 1.39 in) | |
| Exhaust | 34.81 ~ 35.01 (1.37 - 1.38 in) | |
| Journal O.D. (mm) | 25.951 ~ 25.970 (1.02 - 1.022 in) | |
| Bearing oil clearance (mm) | 0.05 ~ 0.09 (0.002 - 0.0035 in) | |
| End play (mm) | 0.1 ~ 0.2 (0.0039 - 0.0079 in) | |
| Cylinder head | | |
| Flatness of gasket surface (mm) | 0.03 (0.0012 in) | |
| Flatness of manifold mounting surface | | |
| (mm) | | |
| Intake | Max 0.5 (0.0197 in) | |
| Exhaust | Max 0.15 (0.0059 in) | |

G00368053

| Helpmelearn | | |
|-----------------------|--------|--|
| June-06-08 8:54:36 AM | Page 1 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona

Fig. 1: General Specifications
Courtesy of KIA MOTORS AMERICA, INC.

| Description | Specification | Limit |
|---------------------------------------|-----------------------------------|---|
| - Dodd iption | 3.5 | Lillit |
| Diameter of valve guide hole (mm) | | |
| 0.05 OS | 12.05 - 12.068 (0.474 - 0.475 in) | |
| 0.25 OS | 12.25 - 12.268 (0.482 - 0.483 in) | |
| 0.50 OS | 12.50 - 12.518 (0.492 - 0.493 in) | |
| Diameter of seat ring hole of intake | | |
| valve (mm) | | |
| 0.3 OS | 36.30 - 36.325 (1.429 -1.430 in) | |
| 0.6 OS | 36.60 - 36.625 (1.441 - 1.442 in) | |
| Diameter of seat ring hole of exhaust | | |
| valve (mm) | | |
| 0.3 OS | 33.30 - 33.325 (1.311 - 1.312 in) | |
| 0.6 OS | 33.60 - 33.625 (1.323 - 1.324 in) | |
| Valve | | |
| Valve length (mm) | | |
| Intake | 106.28 (4.18 in) | |
| Exhaust | 105.4 (4.15 in) | |
| Outer diameter of stem | | |
| Intake | 6.565 - 6.580 (0.258 - 0.259 in) | |
| Exhaust | 6.530 - 6.550 (0.0257 - 0.258 in) | |
| Face angle | 45°- 45.5° | |
| Seat width (Margin) | | |
| Intake (mm) | 1.0 (0.039 in) | 0.5 (0.02 in) |
| Exhaust (mm) | 1.5 (0.059 in) | 1.0 (0.039 in) |
| Clearance (Between stem and guide) | | |
| Intake (mm) | 0.02 - 0.05 (0.0009 - 0.0020 in) | 0.1 (0.0039 in) |
| Exhaust (mm) | 0.05 - 0.085 (0.002 - 0.0033 in) | 0.15 (0.0059 in) |
| Valve spring | | |
| Free length | 46.4 (1.8268 in) | |
| Load (kg/mm) | | |
| К1 | 2.816 | K1: Spring constant who |
| К2 | 3.535 | installing the valve K2: Spring constant who |
| Rectangularity | 2° | lifting the valve |
| Piston (mm) | | |
| Outer diameter | 92.96 - 92.99 (3.66 - 3.661 in) | |
| Clearance (Between piston and | 0.03 - 0.05 (0.0012 - 0.0020 in) | |
| cylinder) | | |

Fig. 2: General Specifications

| Helpmelearn | | | |
|-----------------------|--------|--|--|
| June-06-08 8:54:28 AM | Page 2 | © 2005 Mitchell Repair Information Company, LLC. | |

2002 ENGINES 3.5L V6 - Sedona

Courtesy of KIA MOTORS AMERICA, INC.

| Description | Specification | Limit | |
|-------------------------------------|---|--------------------|--|
| Description | 3.5 | | |
| Width of ring groove (mm) | | | |
| No. 1 | 1.503 - 1.505 (0.0592 - 0.0593 in) | | |
| No. 2 | 1.501 - 1.503 (0.0591 - 0.0592 in) | | |
| Oil | 3.010 - 3.030 (0.1185 - 0.1193 in) | | |
| Rings for Service | 0.25, 0.50, 0.75, | | |
| | 1.00, oversize | | |
| Piston Ring | | | |
| Number of rings per piston | 3 | | |
| Compression ring | 2 | | |
| Oil ring | 1 | | |
| Compression ring type | | | |
| No. 1 | Barral & innerbevel type | | |
| No. 2 | Taper & undercut type | | |
| Oil ring type | 3-piece type | | |
| Ring end gap | | | |
| No. 1 | 0.20 - 0.30 mm (0.0079 - 0.0118 in) | 0.8 mm (0.031 in) | |
| No. 2 | 0.45 - 0.60 mm (0.0177 - 0.0236 in) | 0.8 mm (0.031 in) | |
| Oil ring side rail | 0.2 - 0.7 mm (0.0079 - 0.0276 in) | 1 mm (0.039 in) | |
| Ring side clearance | | | |
| No. 1 | 0.04 - 0.08 mm (0.0016 - 0.0315 in) | 0.1mm (0.0039 in) | |
| No. 2 | 0.02 - 0.06 mm (0.0008 - 0.0024 in) | 0.1mm (0.0039 in) | |
| Rings for Service | 0.25, 0.50, 0.75, 1.00, oversize | | |
| Connecting rod | | | |
| Side clearance | 0.1 - 0.25 mm (0.00394 - 0.00984 in) | 0.4 mm (0.016 in) | |
| Bend | 0.05 or less/100 mm (0.002 in or less / 3.937 in) | | |
| Bearing oil clearance | 0.022 - 0.040 mm (0.0009 - 0.0016 in) | 0.1mm (0.0039 in) | |
| Crankshaft | - | | |
| Journal O.D. | 63.982 - 64.00 mm (2.5190 - 2.5197 in) | | |
| Pin O.D. | 54.982 - 55.000 mm (2.1650 - 2.1654 in) | | |
| Out-of-roundness of journal and pin | 0.003 mm (0.00018 in) | | |
| end play | 0.05 - 0.25 mm (0.002 - 0.01 in) | 0.35 mm (0.014 in) | |
| Main bearing oil clearance | 0.018 ~ 0.036 mm (0.0071 - 0.0014 in) | | |

Fig. 3: General Specifications Courtesy of KIA MOTORS AMERICA, INC.

| Helpmelearn | | |
|-----------------------|--------|--|
| June-06-08 8:54:28 AM | Page 3 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona

| Description | Description Specification | | Specification | |
|---------------------------------|--|--------------------|---------------|--|
| Description | 3.5 | Limit | | |
| Cylinder block | | | | |
| Cylinder bore | 93.0 mm (3.6614 in) | | | |
| Flatness of gasket surface | 0.05 mm (0.002 in) | 0.2 mm (0.0079 in) | | |
| Out-of-roundness | ø0.02 mm (0.00079 in) | | | |
| Oil pump | | | | |
| Side clearance | | | | |
| Body clearance | 0.1 - 0.181 mm (0.0039 - 0.0071 in) | | | |
| Side clearance | 0.04 - 0.095 mm (0.0016 - 0.0037 in) | | | |
| Relief Spring | | | | |
| Free length | 46.3 mm (1.823 in) | | | |
| Load | 3.43kg / 39.1 mm (1.56 lb/1.54 in) | | | |
| Oil filter type | Catridge | | | |
| | Full flow | | | |
| Engine oil pressure | 640kPa (Conditions: Oil temp is 194~230°F, 90~110°C) | | | |
| Engine oil quantity | 4.3 l (4.51 US.qts, 3.78 Imp.qts) | | | |
| Cooling method | Engine coolant cooling, forced circulation with | | | |
| | electric fan | | | |
| Cooling system quantity | 8.2 <i>i</i> (8.61 US.qts, 7.2 Imp.qts) | | | |
| Thermostat | | | | |
| Туре | Wax pellet type with jiggle valve | | | |
| Normal opening temperature (°C) | 82 (179.6 °F) | | | |
| Opening temperature range (°C) | 80 - 84 (176 - 183.2 °F) | | | |
| Wide open temperature (°C) | 95 (203 °F) | | | |
| Radiator | | | | |
| Main valve opening pressure | 93.2 - 122.6 kPa | | | |
| | (0.95 - 1.25kg/cm², 13.5 - 17.8 psi) | | | |
| Vaccum valve opening pressure | -0.98 - 4.90 kPa | | | |
| | (-0.01 - 0.05kg/cm², -0.14 - 0.71 psi) | | | |
| Air cleaner | | | | |
| Туре | Dry type | | | |
| Element | Unwoven cloth type | | | |
| Exhaust pipe | | | | |
| Muffler | Expansion resonance type | | | |
| Suspension system | Rubber hanger | | | |

Fig. 4: General Specifications
Courtesy of KIA MOTORS AMERICA, INC.

TORQUE SPECIFICATIONS

| Helpmelearn | | | |
|-----------------------|--------|--|--|
| June-06-08 8:54:28 AM | Page 4 | © 2005 Mitchell Repair Information Company, LLC. | |

2002 ENGINES 3.5L V6 - Sedona

TORQUE SPECIFICATIONS

| Application | Ft. Lbs. (N.m) |
|---|------------------------------|
| Air Intake Surge Tank-To-Intake Manifold Bolt\Nut | 11-15 (15-20) |
| Auto Tensioner Fixing Bolt | 15-20 (20-27) |
| Camshaft Bearing Cap Bolt (1) | |
| Inner Bolt | (2) |
| Outer Bolt | 14-15 (19-21) |
| Camshaft Sprocket Bolt | 58-72 (79-98) |
| Catalytic Converter Nut | 22-30 (30-40) |
| Center Exhaust Pipe Nut | 22-30 (30-40) |
| Connecting Rod Nut | |
| Step 1 | 26 (35) |
| Step 2 | Plus Torque Angle 92 Degrees |
| Crankshaft Main Bearing Cap Bolt (1) | 51-58 (69-79) |
| Crankshaft Pulley Bolt | 133-140 (180-190) |
| Cylinder Head Bolts (3) | 77-85 (105-115) |
| Drive Belt Pulley Bolt | 26-41 (35-55) |
| Drive Belt Tensioner Nut | 33-37 (45-50) |
| Drive Plate & Adapter Plate Bolt | 54-57 (73-77) |
| Engine Cooling Inlet Fitting Attaching Bolt | 13-15 (17-20) |
| Engine Coolant Pump Bolt | |
| M8 | 11-16 (15-22) |
| M10 | 24-37 (33-50) |
| Engine Coolant Temperature Sensor & Gauge Unit Bolt | 15-30 (20-40) |
| Engine Hanger Bracket Bolt | 20-26 (27-35) |
| Exhaust Manifold Nut | 20-24 (27-32) |
| Front Exhaust Pipe-To-Converter Bolt | 30-44 (40-60) |
| Front Exhaust Pipe-To-Manifold Nut | 22-30 (30-40) |
| Generator Mount Bolt (Bracket Side) | 15-22 (20-30) |
| Generator Mount Bracket-To-Engine Bolt | 15-22 (20-30) |
| Generator Mount Nut (Engine Front Case Side) | 15-22 (20-30) |
| Intake Manifold Surge Tank Stay Bolt | 11-15 (15-20) |
| Intake Manifold-To-Cylinder Head Bolt (4) | 15-17 (20-23) |
| Oil Pan Drain Plug | 26-33 (35-45) |
| Oil Relief Valve Plug | 30-37 (40-50) |
| Oil Screen Bolt | 11-16 (15-22) |
| Oxygen Sensor | 30-37 (40-50) |
| Power Steering Oil Pump Bracket-To-Cylinder Head Bolt | 13-19 (17-26) |
| Power Steering Oil Pump-To-Bracket Bolt | 13-19 (17-26) |
| Starter-To-Engine Bolt | 20-25 (27-34) |
| | · / |

Page 5

© 2005 Mitchell Repair Information Company, LLC.

June-06-08 8:54:28 AM

2002 ENGINES 3.5L V6 - Sedona

| Starter-To-Engine Nut | 15-22 (20-30) | |
|---|-----------------|--|
| Timing Belt Cover Bolt | | |
| M6 Bolt | (2) | |
| M8 Bolt | 15-20 (20-27) | |
| Timing Belt Idler Pulley Bolt | 37-44 (50-60) | |
| Timing Belt Tensioner Arm Fixing Bolt | 26-41 (35-55) | |
| Timing Belt Tensioner Pulley Bolt | 32-41 (43-55) | |
| Upper Oil Pan Bolt (10x38 mm) (5) | 22-31 (30-42) | |
| Water Outlet Fitting Bolt | 13-15 (17-20) | |
| , | INCH Lbs. (N.m) | |
| Air Cleaner Mounting Bolt | 71-106 (8-12) | |
| Crank Position Sensor Wheel Screw | 44-53 (5-6) | |
| Cylinder Head Cover Bolt ⁽⁶⁾ | 71-89 (8-10) | |
| Delivery Pipe Installation Bolt | 89-133 (10-15) | |
| Fuel Hose Clamp | 106-133 (12-15) | |
| Generator Inlet Pipe-To-Front Cylinder Head Assembly Bolt | 106-133 (12-15) | |
| Heat Shield-To-Exhaust Manifold Bolt | 106-133 (12-15) | |
| Lower Oil Pan Bolt ⁽⁷⁾ | 89-106 (10-12) | |
| Main Muffler Hanger Support Bracket Bolt | 89-133 (10-15) | |
| Oil Filter | 106-142 (12-16) | |
| Oil Level Gauge Guide-To-Engine Bolt | 106-133 (12-15) | |
| Oil Pressure Switch | 71-106 (8-12) | |
| Oil Pump Case Bolts | 106-133 (12-15) | |
| Oil Pump Cover Screw | 71-133 (8-15) | |
| Oil Seal Case Bolt | 89-106 (10-12) | |
| Upper Oil Pan Bolt | | |
| 171.5 mm | 44-62 (5-7) | |
| 152.5 mm | 44-62 (5-7) | |
| Rear Plate Bolt | 89-106 (10-12) | |
| Throttle Body-To-Surge Tank Bolt | 89-115 (10-13) | |
| Transaxle Mounting Plate Bolt | 89-106 (10-12) | |
| (1) Tighten bolts evenly in 3-4 steps to specification. | | |
| (2) Tighten bolt to 89-106 INCH lbs. (10-12 N.m) | | |
| (3) Tighten in sequence to specification. See <u>Fig. 5</u> . | | |
| $^{(4)}$ Tighten in sequence to specification. See <u>Fig. 6</u> . | | |
| (5) Tighten in sequence to specification. See $\underline{\mathbf{Fig. 7}}$. | | |
| (6) Tighten in sequence to specification. See $\underline{\mathbf{Fig. 8}}$. | | |
| Tighten in sequence to specification. See Fig. 9 . | | |
| Helpmelearn | | |

Page 6

© 2005 Mitchell Repair Information Company, LLC.

June-06-08 8:54:28 AM

(7)




Fig. 5: Cylinder Head Bolt Tightening Sequence Courtesy of KIA MOTORS AMERICA, INC.

| Helpmelearn | | |
|-----------------------|--------|--|
| June-06-08 8:54:28 AM | Page 7 | © 2005 Mitchell Repair Information Company, LLC. |




Fig. 6: Intake Manifold Nut Tightening Sequence Courtesy of KIA MOTORS AMERICA, INC.

| Helpmelearn | | |
|-----------------------|--------|--|
| June-06-08 8:54:28 AM | Page 8 | © 2005 Mitchell Repair Information Company, LLC. |




Fig. 7: Upper Oil Pan Bolt Tightening Sequence Courtesy of KIA MOTORS AMERICA, INC.

| Helpmelearn | | |
|-----------------------|--------|--|
| June-06-08 8:54:28 AM | Page 9 | © 2005 Mitchell Repair Information Company, LLC. |




Fig. 8: Cylinder Head Cover Bolt Tightening Sequence Courtesy of KIA MOTORS AMERICA, INC.

| Helpmelearn | | | |
|-----------------------|---------|--|--|
| June-06-08 8:54:28 AM | Page 10 | © 2005 Mitchell Repair Information Company, LLC. | |

2002 ENGINES 3.5L V6 - Sedona




Fig. 9: Lower Oil Pan Bolt Tightening Sequence Courtesy of KIA MOTORS AMERICA, INC.

FLUIDS

ANTIFREEZE SERVICE STANDARD

| Standard | |
|----------------------------------|----------|
| Antifreeze coolant concentration | 40 ~ 50% |

G00320515

Fig. 10: Antifreeze Service Standard Chart Courtesy of KIA MOTORS AMERICA, INC.

| Helpmelearn | | |
|-----------------------|---------|--|
| June-06-08 8:54:28 AM | Page 11 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona

ANTIFREEZE COOLANT

| Antifreeze coolant | Ethylene glycol for aluminum radiator |
|--------------------|---------------------------------------|
| G00320516 | |

Fig. 11: Antifreeze Coolant Chart Courtesy of KIA MOTORS AMERICA, INC.

SEALANT

| Water temperature sensor and gauge unit | No.2310 of Three Bond Co. or equivalent |
|---|---|
| Rocker cover | Roctite No.5699 or Three Bond No. 1141E |
| PCV valve | Loctite No. 242 or equivalent |

G00320517

Fig. 12: Sealant Chart Courtesy of KIA MOTORS AMERICA, INC.

SPECIAL SERVICE TOOLS

| Tool (Number and name) | Illustration | Use |
|---|--------------|--|
| Valve spring compressor (09222-28000) (09222-28100) | | Removal and installation of intake and exhaust valve |
| Valve stem oil seal installer (09222-22001) | | Installation of valve stem oil seal |
| Valve guide installer (09222-22000(B)) (09221-29000(A)) | | Removal and installation of valve guide |

G00368057

Fig. 13: Special Service Tools
Courtesy of KIA MOTORS AMERICA, INC.

| Helpmelearn | | | |
|-----------------------|---------|--|--|
| June-06-08 8:54:28 AM | Page 12 | © 2005 Mitchell Repair Information Company, LLC. | |

2002 ENGINES 3.5L V6 - Sedona

| Tool (Number and name) | Illustration | Use |
|--|--------------|--|
| 09231-33000 Crankshaft rear oil seal installer | | Installation of crankshaft rear oil seal |
| 09214-33000 Crankshaft front oil seal installer | | Installation of crankshaft front oil seal |
| 09221-21000 Camshaft oil seal installer | | Installation of camshaft oil seal |
| 09234-33001 Piston pin remover and installer | | Removal and installation of piston pin |
| 09231-33100 Crankshaft wrench | | Used if the crankshaft needs to be rotated to attach the timing belt, etc. |
| 09222-29000 Valve stem oil seal remover | | Removal of valve stem oil seal |
| 09188-38000 Spark plug socket wrench | u D | Installation and removal of spark plug |
| 09263-38000 Oil filter wrench | | Removal of oil filter |

G00368058

Fig. 14: Special Service Tools
Courtesy of KIA MOTORS AMERICA, INC.

CHECKING COMPRESSION PRESSURE

- 1. Before checking compression, check the engine oil level and that the starter motor and battery are all in normal operating condition.
- 2. Start the engine and wait until engine coolant temperature has risen to 80-95°C
- 3. Stop the engine and disconnect the spark plug cables.

| Helpmelearn | | |
|-----------------------|---------|--|
| June-06-08 8:54:28 AM | Page 13 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona

- 4. Remove the spark plugs.
- 5. Turn over the engine to remove any foreign objects in the cylinders.
- 6. Attach the compression gauge to the spark plug hole.
- 7. Depress the accelerator pedal to fully open the throttle valve.
- 8. Turn over the engine and read the gauge.

Standard value: 1,200 kPa (12.2 kg.cm², 170 psi)

Limit: 1,050 kPa (10.7 kg.cm², 149 psi)




Fig. 15: Testing Compression Courtesy of KIA MOTORS AMERICA, INC.

9. Repeat steps 6 through 8 on all cylinders, making sure ensuring that the pressure difference for each of the cylinders is within the specified limit.

Limit: Max 100 kPa (1.0 kg/cm², 14 psi) for all cylinders.

| Helpmelearn | | | |
|-----------------------|---------|--|--|
| June-06-08 8:54:28 AM | Page 14 | © 2005 Mitchell Repair Information Company, LLC. | |

2002 ENGINES 3.5L V6 - Sedona

- 10. If a cylinder's compression or pressure difference is below the specification, add a small amount of oil through the spark plug hole and repeat steps 6 through 9.
 - a. If the addition of oil causes the compression to rise, it is possible that there is wear between the piston ring and cylinder wall.
 - b. If the compression doesn't rise, valve seizure, poor valve seating or a compression leak from the cylinder head gasket are all possible causes.

Spark plug tightening torque: 20-30 N.m (200 - 300 kg.cm, 14.75 - 22.13 lb.ft.)

ENGINE OIL

CHECKING ENGINE OIL

- 1. Position vehicle on a level surface
- 2. Stop the engine

CAUTION: In the case of a vehicle that has been out of service for a prolonged period, run the engine for several minutes. Stop the engine and wait a few minutes, then check the oil level.

3. If the oil is found to have fallen to the lower limit (the L mark), refill to the (F) mark.

CAUTION: When filling, use the same type of engine oil as the one currently being used.


4. Check that the oil is not dirty or mixed with coolant or gasoline, and that it has the proper viscosity.

SELECTION OF ENGINE OIL

- Recommended API classification : SD or above.
- Recommended SAE viscosity grades:

| Helpmelearn | | |
|-----------------------|---------|--|
| June-06-08 8:54:28 AM | Page 15 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona



- *1. Restricted by driving & climate condition.
- *2. Not recommended for sustained high speed vehicle operation.

G00368060

NOTE:

Fig. 16: Recommended Oil Viscosity Chart

Courtesy of KIA MOTORS AMERICA, INC.

For best performance and for maximum protection for all types of operation, select only those lubricants which:

- a. Confirm to the requirements of the API classification.
- b. Have proper SAE grade number for expected ambient temperature range. Lubricants which do not have both an SAE grade number and an API service classification on the container should not be used.

| Helpmelearn | | |
|-----------------------|---------|--|
| June-06-08 8:54:28 AM | Page 16 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona

CHANGING ENGINE OIL

- 1. Runt the engine until it reaches normal operating temperature.
- 2. Stop the engine.
- 3. Remove the oil filler cap and the drain plug. Drain the engine oil.




Fig. 17: Identifying Oil Drain Plug Courtesy of KIA MOTORS AMERICA, INC.

4. Tighten the drain plug to the specified torque. 26-30 ft.lbs. (35-45 N.m).

CAUTION: Whenever tightening an oil drain plug, use a new drain plug gasket.

- 5. Install oil filter.
- 6. Fill the engine with new engine oil through the oil filling hole. Amount of oil 4.5 qts (4.3Liters))

CAUTION: Do not overfill the crankcase. This will cause oil aeration and loss of oil pressure.

| Helpmelearn | | |
|-----------------------|---------|--|
| June-06-08 8:54:29 AM | Page 17 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona

- 7. Reinstall the oil filler cap.
- 8. Start the engine.
- 9. Stop the engine and check the oil level. If not sufficient, refill engine.

REPLACING OIL FILTER

All Kia Motor Company engines are equipped with a quality, throw-away oil filter. This filter is recommended as a replacement filter on all vehicles. The quality of replacement filters varies considerable. Only high quality filters should be used to assure the most efficient service. Make sure that the rubber gasket from the old filter is completely removed from the mating surfaces on the engine block, before installing the new filter.

- 1. Use a filter wrench to remove the oil filter.
- 2. Before installing the new oil filter on the engine, apply clean engine oil to the surface of the rubber gasket.




Fig. 18: Illustrating Oil filter Courtesy of KIA MOTORS AMERICA, INC.

| Helpmelearn | | |
|-----------------------|---------|--|
| June-06-08 8:54:29 AM | Page 18 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona

- 3. Tighten the oil filter to the specified amount. 13-18 ft.lbs. (17-25 N.m))
- 4. Fill the engine with engine oil.
- 5. Start and run the engine and check for oil leaks.
- 6. After stopping the engine, check the oil level and add as much oil as necessary.

OIL PRESSURE SWITCH

- 1. If "OIL PRESSURE" indicating lamp lights when ignition switch is set to "ON" and goes out when engine is started and runs at idle, then everything is in order. If "OIL PRESSURE" lamp does not light when ignition switch is set to "ON" check switch, lamp and wiring.
- 2. If there is current flow when ignition switch is set to "ON" and if there is no current flow when engine is running at idle, switch is good.

If switch is good, check lamp and wiring.

Operating pressure of oil pressure switch: 19.6 - 39.2 kPa (0.2 - 0.4 kg.cm², 2.84 - 5.69 psi)




Fig. 19: Illustrating Oil Pressure Switch Courtesy of KIA MOTORS AMERICA, INC.

3. Using 24 mm deep socket, tighten the switch to the specified torque.


NOTE: Do not tighten the oil pressure switch to the excessive torque.

Tightening torque

| Helpmelearn | | | |
|-----------------------|---------|--|--|
| June-06-08 8:54:29 AM | Page 19 | © 2005 Mitchell Repair Information Company, LLC. | |

2002 ENGINES 3.5L V6 - Sedona

Oil pressure switch and sensor assembly: 8-12 N.m (80~120 kg.cm, 5.91-8.85 lb.ft)



G00320625

Fig. 20: Removing & Installing Oil Pressure Switch Courtesy of KIA MOTORS AMERICA, INC.

DRIVE BELT ROUTING

- 1. For power steering belt routing, see **Fig. 21**.
- 2. For air conditioning compressor and alternator belt routing, see **Fig. 22**.
- 3. For combined belt routing, see **Fig. 23**.

| Helpmelearn | | | |
|-----------------------|---------|--|--|
| June-06-08 8:54:29 AM | Page 20 | © 2005 Mitchell Repair Information Company, LLC. | |




Fig. 21: Power Steering Belt Routing Courtesy of KIA MOTORS AMERICA, INC.

| Helpmelearn | | |
|-----------------------|---------|--|
| June-06-08 8:54:29 AM | Page 21 | © 2005 Mitchell Repair Information Company, LLC. |





Fig. 22: Air Conditioning Compressor & Alternator Belt Routing Courtesy of KIA MOTORS AMERICA, INC.

| Helpmelearn | | | |
|-----------------------|---------|--|--|
| June-06-08 8:54:29 AM | Page 22 | © 2005 Mitchell Repair Information Company, LLC. | |

2002 ENGINES 3.5L V6 - Sedona



- 1. Tension pulley
- 2. Power steering pulley
- 3. Crankshaft pulley
- 4. Alternator pulley
- 5. Air conditioner pulley
- 6. Idler pulley
- 7. Tension pulley

G00323228

Fig. 23: Combined Drive Belt Routing Courtesy of KIA MOTORS AMERICA, INC.

DRIVE BELT ADJUSTMENT

Power Steering

- 1. Loosen hinge bolt "A" and flange nut "B". See Fig. 24.
- 2. Turn adjusting bolt "C" to set belt tension to specified deflection. See <u>Fig. 24</u> and <u>Fig. 25</u>. See <u>BELT ADJUSTMENT</u> table.
- 3. Tighten hinge bolt "A" and flange nut "B" to specification. See **TORQUE SPECIFICATIONS** table.

Alternator & Air Conditioning Compressor

- 1. Loosen pulley lock nut "A". See **Fig. 26**.
- 2. Turn adjustment bolt "B" to set belt tension to specified deflection. See <u>Fig. 26</u> and <u>Fig. 27</u>. See <u>BELT ADJUSTMENT</u> table.
- 3. Tighten pulley lock nut "A" to specification. See **TORQUE SPECIFICATIONS** table.


| Helpmelearn | | |
|-----------------------|---------|--|
| June-06-08 8:54:29 AM | Page 23 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona

- 4. Start engine and turn A/C on.
- 5. Allow vehicle to run until normal operating temperature is reached.
- 6. Turn engine off, recheck belt deflection after operation and readjust belt tension as necessary. See <u>BELT</u> <u>ADJUSTMENT</u> table.

BELT ADJUSTMENT

| Application | (1) Deflection - In. (mm) | |
|---|---------------------------|--|
| Alternator & Air Conditioning Compressor | | |
| New Belt Deflection | .2022 (5-5.5) | |
| Used Belt Deflection | .2428 (6-7) | |
| After Operation | .31 (8) | |
| Power Steering | | |
| New Belt Deflection | .3543 (9-11) | |
| Used Belt Deflection | .4759 (12-15) | |
| (1) Deflection is measured at the contact point with 22 lbs. (10 kg) of deflection force. | | |



| Helpmelearn | | |
|-----------------------|---------|--|
| June-06-08 8:54:29 AM | Page 24 | © 2005 Mitchell Repair Information Company, LLC. |

Fig. 24: Adjusting Power Steering Belt Tension Courtesy of KIA MOTORS AMERICA, INC.




Fig. 25: Measuring Power Steering Belt Deflection Courtesy of KIA MOTORS AMERICA, INC.

| Helpmelearn | | |
|-----------------------|---------|--|
| June-06-08 8:54:29 AM | Page 25 | © 2005 Mitchell Repair Information Company, LLC. |




Fig. 26: Adjusting Alternator & Air Conditioning Compressor Belt Courtesy of KIA MOTORS AMERICA, INC.

| Helpmelearn | | |
|-----------------------|---------|--|
| June-06-08 8:54:29 AM | Page 26 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona




Fig. 27: Measuring Alternator & Air Conditioning Compressor Belt Deflection Courtesy of KIA MOTORS AMERICA, INC.

COOLANT LEAK CHECK

- 1. Loosen the radiator cap.
- 2. Confirm that the coolant level is up to the filler neck.
- 3. Install a radiator cap tester to the radiator filler neck and apply 22 lbs. of pressure. Hold for two minutes in that condition, while checking, hose connections.

| Helpmelearn | | |
|-----------------------|---------|--|
| June-06-08 8:54:29 AM | Page 27 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona




Fig. 28: Pressure Testing Radiator Courtesy of KIA MOTORS AMERICA, INC.

CAUTION:

- Radiator coolant may be extremely hot. Do not open the system while hot, or scalding. Engine coolant could spray out causing personal injury. Allow the vehicle to cool before servicing this system.
- Be sure to completely clean away any moisture from the places checked.
- When the tester is removed, be careful not to spill any coolant from tester.
- Be careful, when installing and removing the tester and when testing, not to deform the filler neck of the radiator.
- 4. If there is any leakage, repair or replace the appropriate part.

RADIATOR CAP PRESSURE TEST

1. Use an adapter to attack the cap to tester.

| Helpmelearn | | |
|-----------------------|---------|--|
| June-06-08 8:54:29 AM | Page 28 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona




Fig. 29: Testing Radiator Cap Courtesy of KIA MOTORS AMERICA, INC.

- 2. Increase the pressure until the gauge indicator stops moving.
 - Main valve opening pressure: 14-18 psi (86-125 kPa).
 - Main valve closing pressure: 12 psi (83 kPa)
- 3. Check that the pressure level is maintained at or above the limit.
- 4. Replace that radiator cap if the reading does not remain at or above the limit.

NOTE: Be sure that the cap is clean before testing, since rust or other foreign material on the cap seal will cause an improper reading.

SPECIFIC GRAVITY TEST

- 1. Measure the specific gravity of the coolant with a hydrometer.
- 2. Measure the coolant temperature, and calculate the concentration from the relation between the specific gravity and temperature, using the following table for reference.

| Helpmelearn | | |
|-----------------------|---------|--|
| June-06-08 8:54:29 AM | Page 29 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona

COOLING SYSTEM SPECIFICATIONS

The coolant concentration can be calculated by measuring coolant temperature and specific gravity. After coolant temperature and specific gravity is obtained, a concentration can be calculated using the following chart. See <u>Fig. 30</u>. If the concentration of coolant is below 30 percent, the anti-corrosion property will be adversely affected. If the concentration is above 60 percent, both the antifreeze and engine cooling properties will decrease and may adversely affect the engine.

NOTE: Recommended coolant concentration is 40-50 percent, using only ethylene glycol for aluminum type coolant.

| Coolant temperature °C (°F) and specific gravity | | | | Safe oper- | Coolant | | |
|--|---------|---------|----------|------------|--------------------------------------|-----------------------------------|--|
| 10 (50) | 20 (68) | 30 (86) | 40 (104) | 50 (122) | Freezing tempera- ture °C (°F) | ating tem- perature °C (°F) | concentra- tion (Spe- cific vol- ume) |
| 1.054 | 1.050 | 1.046 | 1.042 | 1.036 | -16 (3.2) | -11 (12.2) | 30% |
| 1.063 | 1.058 | 1.054 | 1.049 | 1.044 | -20 (-4) | -15 (5) | 35% |
| 1.071 | 1.067 | - 1.062 | 1.057 | 1.052 | -25 (-13) | -20 (-4) | 40% |
| 1.079 | 1.074 | 1.069 | 1.064 | 1.058 | -30 (-22) | -25 (-13) | 45% |
| 1.087 | 1.082 | 1.076 | 1.070 | 1.064 | -36 (-32.8) | -31 (-23.8) | 50% |
| 1.095 | 1.090 | 1.084 | 1.077 | 1.070 | -42 (-44) | -37 (-35) | 55% |
| 1.103 | 1.098 | 1.092 | 1.084 | 1.076 | -50 (-58) | -45 (-49) | 60% |

G00323217


Fig. 30: Testing Coolant Concentration & Specific Gravity Courtesy of KIA MOTORS AMERICA, INC.

ENGINE MOUNTING

ENGINE MOUNTS

| Helpmelearn | | |
|-----------------------|---------|--|
| June-06-08 8:54:29 AM | Page 30 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona



TORQUE: N·m (kg·cm, lb·ft)


G00320529

Fig. 31: Identifying Engine Mounts Courtesy of KIA MOTORS AMERICA, INC.

SUB FRAME MOUNTS

| Helpmelearn | | |
|-----------------------|---------|--|
| June-06-08 8:54:29 AM | Page 31 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona



TORQUE: N·m (kg·cm, lb·ft)

G00320530

Fig. 32: Identifying Subframe Mounts Courtesy of KIA MOTORS AMERICA, INC.

ENGINE AND TRANSAXLE ASSEMBLY

REMOVAL

1. Remove the battery and engine cover.

| Helpmelearn | | |
|-----------------------|---------|--|
| June-06-08 8:54:29 AM | Page 32 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona

- 2. Detach the air cleaner.
- 3. Disconnect the connectors for the engine harness.
- 4. Disconnect the connectors for the alternator harness, the oil pressure switch and the oil pressure sensor.
- 5. Disconnect the connector of starter motor harness.
- 6. Drain the engine coolant.
- 7. Disconnect transaxle oil cooler hose.

NOTE: When disconnecting the hoses, make identification marks to avoid making any mistakes when re-installing them.

CAUTION: Be careful not to spill any of the oil or fluid out of the hoses. Plug the openings to prevent the entry of foreign material.

- 8. Disconnect the radiator upper and lower hoses on the engine side, and then remove the radiator assembly.
- 9. Disconnect the high tension cable and all wires to the distributor and the ignition coil.
- 10. Disconnect the engine ground.
- 11. Disconnect the brake booster vacuum hose.
- 12. Disconnect the EVAP canister hose.
- 13. Remove the main fuel line, and the return and vapor hoses from the engine side.

CAUTION: To reduce the residual pressure in the hoses, see <u>FUEL PRESSURE</u> TEST.

- 14. Disconnect the heater hose (Intake and exhaust) at the engine side.
- 15. The accelerator cable should be removed from the engine side.
- 16. The cruise control cable should be removed from the engine side.
- 17. Remove the control cable from the transaxle.
- 18. Disconnect the speed sensor connector from the transaxle.

| Helpmelearn | | |
|-----------------------|---------|--|
| June-06-08 8:54:29 AM | Page 33 | © 2005 Mitchell Repair Information Company, LLC. |




Fig. 33: Disconnecting The Speed Sensor Connector Courtesy of KIA MOTORS AMERICA, INC.

- 19. Remove the power steering oil pump hose.
- 20. Raise the vehicle.
- 21. Remove the oil pan shield.
- 22. Drain the transaxle oil.

| Helpmelearn | | |
|-----------------------|---------|--|
| June-06-08 8:54:29 AM | Page 34 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona




Fig. 34: Drain The Transaxle Oil Courtesy of KIA MOTORS AMERICA, INC.

23. Disconnect the front exhaust pipe from the manifold.

NOTE: Use a wire to suspend the exhaust pipe from the bottom of the vehicle.

- 24. Remove the tie rod end from steering knuckles.
- 25. Remove control link from stabilizer and lower arm.
- 26. Remove pinch bolt from knuckle. Separate lower arm form knuckle.

| Helpmelearn | | |
|-----------------------|---------|--|
| June-06-08 8:54:29 AM | Page 35 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona




Fig. 35: Removing Pinch Bolt From Knuckle Courtesy of KIA MOTORS AMERICA, INC.

27. Remove the drive shaft from the transaxle housing.

CAUTION:

- Plug up the holes of the transaxle case to prevent entry of foreign material.
- The circlips on the drive shafts should be replaced whenever reinstalling.

| Helpmelearn | | |
|-----------------------|---------|--|
| June-06-08 8:54:29 AM | Page 36 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona




Fig. 36: Removing The Drive Shaft From The Transaxle Housing Courtesy of KIA MOTORS AMERICA, INC.

- 28. Remove intermediate shaft bolt. See **REMOVAL**.
- 29. Remove No. 3, No. 4 engine mounting.
- 30. Support auto transaxle, engine and subframe with a suitable floor jack.

| Helpmelearn | | |
|-----------------------|---------|--|
| June-06-08 8:54:29 AM | Page 37 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona




Fig. 37: Support Auto Transaxle, Engine & Subframe With A Suitable Floor Jack Courtesy of KIA MOTORS AMERICA, INC.

- 31. Remove nuts and blots of impact bar and subframe.
- 32. Slowly lower engine, auto transaxle and subframe.
- 33. Remove No. 1, No. 2 engine mounting from subframe.
- 34. Separate auto transaxle from engine.


TIMING SYSTEM

| Helpmelearn | | | |
|-----------------------|---------|--|--|
| June-06-08 8:54:29 AM | Page 38 | © 2005 Mitchell Repair Information Company, LLC. | |

2002 ENGINES 3.5L V6 - Sedona

TIMING BELT

COMPONENTS



TORQUE: Nm (kg.cm, lb.ft)


Fig. 38: Identifying Timing System Components Courtesy of KIA MOTORS AMERICA, INC.

REMOVAL

- 1. Remove the engine cover.
- 2. Remove the drive belt.
- 3. Remove the idler pulley, crankshaft pulley, power steering pulley and tensioner pulley.

| Helpmelearn | | |
|-----------------------|---------|--|
| June-06-08 8:54:29 AM | Page 39 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona




G00320684

Fig. 39: Identifying Belt Routing Courtesy of KIA MOTORS AMERICA, INC.

4. Remove the upper and lower timing belt cover.

| Helpmelearn | | |
|-----------------------|---------|--|
| June-06-08 8:54:29 AM | Page 40 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona



G00320685

Fig. 40: Removing The Upper & Lower Timing Belt Cover Courtesy of KIA MOTORS AMERICA, INC.


5. Support the engine with garage jack or special tool, and then remove the engine mounting insulator.

CAUTION: Take care not to deform the engine oil pan.

6. Remove the auto tensioner.

| Helpmelearn | | |
|-----------------------|---------|--|
| June-06-08 8:54:29 AM | Page 41 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona



G00320686

Fig. 41: Removing The Auto Tensioner Courtesy of KIA MOTORS AMERICA, INC.


NOTE:

Rotate the crankshaft clockwise and align the timing mark to get the No. 1 cylinder's piston be in TDC position (compression stroke). At this time, the timing marks of the camshaft sprocket and cylinder head cover should coincide with each other.

7. Remove the timing belt.

| Helpmelearn | | |
|-----------------------|---------|--|
| June-06-08 8:54:29 AM | Page 42 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona



G00320687

Fig. 42: Remove The Timing Belt Courtesy of KIA MOTORS AMERICA, INC.

NOTE: When re-using timing belt, make sure of marking the rotating direction on the belt so as to install correctly.

INSPECTION

TIMING BELT

Check the belt carefully and if any damage is found, exchange it with a new one.

1. Vulcanization of the rubber backside.

The backside is glossy and non-elastic so that, even if a finger nail is forced into it, no mark is produced.

| Helpmelearn | | |
|-----------------------|---------|--|
| June-06-08 8:54:29 AM | Page 43 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona




Fig. 43: Testing Timing Belt For Vulcanization Courtesy of KIA MOTORS AMERICA, INC.

2. Crack on the rubber belt surface.

| Helpmelearn | | | |
|-----------------------|---------|--|--|
| June-06-08 8:54:29 AM | Page 44 | © 2005 Mitchell Repair Information Company, LLC. | |

2002 ENGINES 3.5L V6 - Sedona





Fig. 44: Testing Timing Belt For Cracks Courtesy of KIA MOTORS AMERICA, INC.

3. Abnormal wearing of side face of belt.

CAUTION: Belts in good condition seem to be cut by a sharp knife.

| Helpmelearn | | |
|-----------------------|---------|--|
| June-06-08 8:54:29 AM | Page 45 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona



G00320690

Fig. 45: Testing Timing Belt For Side Face Wear Courtesy of KIA MOTORS AMERICA, INC.

4. Abnormal tooth wearing

| Helpmelearn | | |
|-----------------------|---------|--|
| June-06-08 8:54:29 AM | Page 46 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona




Fig. 46: Testing Timing Belt For Abnormal Tooth Wear Courtesy of KIA MOTORS AMERICA, INC.

Initial stage

Wearing of side face of load exerting tooth (Fabric puff up, rubber material peel off with color changing to white and fabric become uneven and rough).

Last stage

Fabric wearing of side face of load exerting tooth occurs and rubber is exposed (Length between teeth decrease.).

5. Missing tooth.

TIMING BELT TENSIONER

If any abnormal noise or difficulty in rotating the pulley by hand is noticed, replace the timing belt tensioner and idler pulley.

| Helpmelearn | | |
|-----------------------|---------|--|
| June-06-08 8:54:29 AM | Page 47 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona




Fig. 47: Testing Timing Belt Tensioner Courtesy of KIA MOTORS AMERICA, INC.

INSTALLATION

| Helpmelearn | | |
|-----------------------|---------|--|
| June-06-08 8:54:29 AM | Page 48 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona




Fig. 48: Identifying Timing Belt Positions Courtesy of KIA MOTORS AMERICA, INC.

TIMING BELT AND AUTO TENSIONER

1. Install the idler pulley to the engine support lower bracket.

| Helpmelearn | | |
|-----------------------|---------|--|
| June-06-08 8:54:29 AM | Page 49 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona




Fig. 49: Installing The Idler Pulley To The Engine Support Lower Bracket Courtesy of KIA MOTORS AMERICA, INC.

2. Install the tensioner arm, shaft and plain washer to the cylinder block.

Tightening torque: 35-55 N.m (350-550 kg.cm, 25.82-40.57 lb.ft)

| Helpmelearn | | | |
|-----------------------|---------|--|--|
| June-06-08 8:54:29 AM | Page 50 | © 2005 Mitchell Repair Information Company, LLC. | |

2002 ENGINES 3.5L V6 - Sedona




Fig. 50: Installing The Tensioner Arm, Shaft And Plain Washer To The Cylinder Block Courtesy of KIA MOTORS AMERICA, INC.

3. Install the crankshaft sprocket.

NOTE: Confirm if timing marks coincide with.

| Helpmelearn | | |
|-----------------------|---------|--|
| June-06-08 8:54:29 AM | Page 51 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona





Fig. 51: Installing The Crankshaft Sprocket Courtesy of KIA MOTORS AMERICA, INC.

CAUTION: Align the spacer with a pin, and assemble it exerting even force not to deform the crankshaft sensing blade.

| Helpmelearn | | |
|-----------------------|---------|--|
| June-06-08 8:54:29 AM | Page 52 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona



Crankshaft sprocket

G00320696

Fig. 52: Align The Spacer & Pin Courtesy of KIA MOTORS AMERICA, INC.

4. Install the camshaft sprocket.

| Helpmelearn | | |
|-----------------------|---------|--|
| June-06-08 8:54:30 AM | Page 53 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona

Align it like initial state as shown on the picture.

CAUTION: When installing camshaft sprocket, tighten the bolt holding hexagonal part of camshaft to prevent it from turning.




Fig. 53: Installing & Aligning Camshaft Sprockets Courtesy of KIA MOTORS AMERICA, INC.

5. Install the auto tensioner to the oil pump case.

CAUTION: At this time the auto tensioner's set pin should be assembled completely.

| Helpmelearn | | |
|-----------------------|---------|--|
| June-06-08 8:54:30 AM | Page 54 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona





Fig. 54: Installing The Auto Tensioner To The Oil Pump Case Courtesy of KIA MOTORS AMERICA, INC.

6. Align the timing marks of each sprocket and install the timing belt, maintaining the proper belt tension between each shaft in this order.

Crankshaft sprocket, Idler pulley, Left bank exhaust camshaft sprocket, Left bank intake camshaft sprocket, Water pump pulley, Right bank intake camshaft sprocket, Right bank exhaust camshaft sprocket and Tensioner pulley.

| Helpmelearn | | |
|-----------------------|---------|--|
| June-06-08 8:54:30 AM | Page 55 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona



G00320699

Fig. 55: Identifying Timing Belt Routing Courtesy of KIA MOTORS AMERICA, INC.

CAUTION:

- As a result of this, position of No. 1 cylinder comes to compression TDC.
- As each camshaft sprocket tends to rotate by itself, pay attention not to injure fingers or other bodily part. Especially be careful with the right bank.
- In case the right bank camshaft sprocket rotates excessively, be cautious not to rotate more than the initial stable position.
 Always align timing mark of rotating sprocket by turning it reversely. In this case, pay attention not to rotate it reversely from the initial position. (If, with one sprocket fixed at No. 1

| Helpmelearn | | |
|-----------------------|---------|--|
| June-06-08 8:54:30 AM | Page 56 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona

compression TDC position, the other sprocket is rotated one revolution clockwise or counter clockwise, then the intake and exhaust valve might interfere each other.)

- 7. After installing the timing belt, exert the reverse-directed force to the right bank exhaust camshaft sprocket to give tension on the belt. Holding this state, recheck if each timing mark is correctly positioned.
- 8. With tensioner pulley slightly pushing the belt down, tighten the center bolts lightly.




Fig. 56: Exerting The Reverse-Directed Force To The Right Bank Exhaust Camshaft Sprocket Courtesy of KIA MOTORS AMERICA, INC.

9. Pull out the auto tensioner set pin.

ADJUSTING TIMING BELT TENSION

- 1. Tension setting (While auto tensioner is not operating: And set pin being kept installed.).
 - 1. After rotating crankshaft 1/4 revolution reversely, rotate it clockwise to position No. 1 cylinder at TDC.

Then, loosen the center bolt and give the belt 50kg-cm of tension with tensioner pulley socket (Two

| Helpmelearn | | |
|-----------------------|---------|--|
| June-06-08 8:54:30 AM | Page 57 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona

pins are attached) and torque wrench. While maintaining this state, tighten the center bolt to the standard torque.

Center bolt standard torque: 43-55 N.m (430-550 kg.cm, 31.72-40.57 lb.ft)




Fig. 57: Tensioning Timing Belt Courtesy of KIA MOTORS AMERICA, INC.

2. Pull out the auto tensioner fixing pin.

| Helpmelearn | | |
|-----------------------|---------|--|
| June-06-08 8:54:30 AM | Page 58 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona




Fig. 58: Removing Auto Tensioner Fixing Pin Courtesy of KIA MOTORS AMERICA, INC.

- 2. How to check tension (While auto tensioner is operating: and fixing pin being uninstalled.)
 - a. After rotating crankshaft 2 revolutions clockwise to position No. 1 cylinder at TDC, wait for about 5 minutes, and measure the amount of protruding of the auto tensioner rod.

CAUTION: This is "leak down" time for the auto tensioner rod to protrude 1mm when tension caused by rotation of the crankshaft has changed.

b. Check if the amount of rod protruding is in the range of 3.8~4.5mm.

| Helpmelearn | | |
|-----------------------|---------|--|
| June-06-08 8:54:30 AM | Page 59 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona




Fig. 59: Measuring The Amount Of Rod Protruding From Auto Tensioner Courtesy of KIA MOTORS AMERICA, INC.

c. Recheck if each sprocket is within the specified range.


NOTE: If it is not within the specified range, repeat from <u>TIMING BELT AND AUTO TENSIONER</u>.

CAMSHAFT

COMPONENTS

| Helpmelearn | | |
|-----------------------|---------|--|
| June-06-08 8:54:30 AM | Page 60 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona



TORQUE: N-m (kg-cm, lb-ft)

G00320536

Fig. 60: Exploded View Of Camshaft Components Courtesy of KIA MOTORS AMERICA, INC.

REMOVAL

1. Remove the cylinder head cover.

| Helpmelearn | | |
|-----------------------|---------|--|
| June-06-08 8:54:30 AM | Page 61 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona





Fig. 61: Removing Cylinder Head Cover

| Helpmelearn | | |
|-----------------------|---------|--|
| June-06-08 8:54:30 AM | Page 62 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona

Courtesy of KIA MOTORS AMERICA, INC.

2. Remove the front bearing cap.



G00320538

Fig. 62: Removing Front Bearing Cover Courtesy of KIA MOTORS AMERICA, INC.

- 3. Remove the rear bearing cap.
- 4. Remove the bearing cap.
- 5. Remove the camshaft oil seal.
- 6. Remove the camshaft.
- 7. Remove the rocker arm.
- 8. Remove the lash adjustor.

| Helpmelearn | | |
|-----------------------|---------|--|
| June-06-08 8:54:30 AM | Page 63 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona




Fig. 63: Identifying Camshaft Components
Courtesy of KIA MOTORS AMERICA, INC.

INSPECTION

CAMSHAFT

1. If there is excessive wear or damage on the camshaft journal or/and cam lobe after checking, replace it with a new one. Measure the height of cam and if the readings are beyond the specification, replace it.

Standard value:

Intake: 35.198 mm (1.385 in)

Exhaust: 34.910 mm (1.375 in)

| Helpmelearn | | |
|-----------------------|---------|--|
| June-06-08 8:54:30 AM | Page 64 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona




Fig. 64: Measuring Camshaft Wear Courtesy of KIA MOTORS AMERICA, INC.

ROCKER ARM

- 1. Inspect the roller visually, if any damage or crack is found, replace it.
- 2. Check that the roller rotates smoothly. If there is excessive clearance, replace it.

LEAK DOWN TEST OF LASH ADJUSTER

CAUTION:

- As the lash adjuster is a precise part, take care not to let any dust and foreign object enter.
- Do not disassemble the lash adjuster.
- Only light oil should be used to clean the lash adjuster
- 1. Immerse the lash adjuster in light oil.
- 2. Push out the steel ball in the lash adjuster softly using the special tool (Air bleed wire 09246-32200) and

| Helpmelearn | | |
|-----------------------|---------|--|
| June-06-08 8:54:30 AM | Page 65 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona

shake the plunger upward and downward 4 or 5 times. Using the special tool (09246-32100), release air from the rocker arm installation type lash adjuster.




Fig. 65: Releasing Air From Lash Adjuster Courtesy of KIA MOTORS AMERICA, INC.

CAUTION: As the ball weight is very small (just a few grams), pushing the special tool excessively can damage the lash adjuster. Push it with care and appropriate force.

3. Take away the special tool (09246-32200) and push the plunger. If it feels tight, the lash adjuster is normal. If it feels soft and easy, then release air from plunger feels and test again. If the plunger feels still soft even after releasing air, replace it.

CAUTION: After releasing air, put the lash adjuster straight up not to spill the oil over, and make sure there is no dust or foreign material on it.

| Helpmelearn | | |
|-----------------------|---------|--|
| June-06-08 8:54:30 AM | Page 66 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona

- 4. After finishing the air release, place the lash adjuster on the special tool (09246-32300).
- 5. After the plunger has gone down around 0.2~0.5mm, measure the time for the plunger to go down additional 1mm. Replace it if the time is out of standard range. Standard dropping down rate: 2~16.5sec/mm (Light oil, oil temperature 20~30°C)




Fig. 66: Measuring Lash Adjuster Drop Courtesy of KIA MOTORS AMERICA, INC.

ADJUSTMENT OF ROCKER ARM CLEARANCE

- 1. Replace the rocker arm with the one specially made for measurement.
- 2. After positioning the rocker arm roller on basic circle of camshaft, push down the ball lightly with special tool (09246-32200) and push down the rocker arm by hand. Maintaining that state, measure the thickness

| Helpmelearn | | |
|-----------------------|---------|--|
| June-06-08 8:54:30 AM | Page 67 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona

by inserting a thickness gauge between the camshaft and rocker arm.

Clearance between camshaft (Basic circle) and rocker arm (roller): 0.7+/-0.25 mm (0.0276+/-0.0098 in)




Fig. 67: Measuring Rocker Arm Clearance Courtesy of KIA MOTORS AMERICA, INC.

CAUTION: As the ball weight is very small (just a few grams), pushing the special tool excessively can damage the lash adjuster. Push it with care and appropriate force.


INSTALLATION

CAMSHAFT AND BEARING CAP

| Helpmelearn | | |
|-----------------------|---------|--|
| June-06-08 8:54:30 AM | Page 68 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona

- 1. Rotate the crankshaft and No. 1 cylinder is in TDC. (Compression stroke)
- 2. Check the position of the rocker arm whether it is exactly installed on the lash adjuster and valve or not.
- 3. Install the camshaft dowel pin as shown.



| Helpmelearn | | |
|-----------------------|---------|--|
| June-06-08 8:54:30 AM | Page 69 | © 2005 Mitchell Repair Information Company, LLC. |


2002 ENGINES 3.5L V6 - Sedona

Fig. 68: Installing Camshaft Dowel Pin Courtesy of KIA MOTORS AMERICA, INC.

4. The left and right banks of the camshafts are different and you should be careful not to confuse them. For camshaft identification, see identification signal below.

CAMSHAFT IDENTIFICATION SIGNAL

| Application | Identification Signal |
|-------------|-----------------------|
| Left Bank | |
| Intake | F |
| Exhaust | E |
| Right Bank | |
| Intake | G |
| Exhaust | Н |






Fig. 69: Illustrating Camshaft Inscribing Position Courtesy of KIA MOTORS AMERICA, INC.

5. Confirm the identification mark and the number. Bearing caps of No. 3, No. 4, and No. 5 have the front mark and arrange the front mark upon the cylinder head while installing the bearing caps.

| Helpmelearn | | |
|-----------------------|---------|--|
| June-06-08 8:54:30 AM | Page 70 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona

| Identification mark | |
|---------------------|---|
| Intake (IN) | 1 |
| Exhaust(Ex) | E |

G00320549

Fig. 70: Illustrating Bearing Caps Identification Mark Chart Courtesy of KIA MOTORS AMERICA, INC.




Fig. 71: Illustrating Bearing Caps Identification Marks Courtesy of KIA MOTORS AMERICA, INC.

6. Tighten the bearing cap in two or three steps. Tighten it to the standard torque at the last stage.

Bearing cap standard torque:

16 pieces at the both ends: 21-26 N.m (210-260 kg-cm., 15-19 ft.lbs.)

24 pieces in the middle: 10-12 N.m (100-120 kg.cm, 7.38-8.85 ft.lbs.)

| Helpmelearn | | | |
|-----------------------|---------|--|--|
| June-06-08 8:54:30 AM | Page 71 | © 2005 Mitchell Repair Information Company, LLC. | |

2002 ENGINES 3.5L V6 - Sedona




Fig. 72: Locating Bearing Cap Positions Courtesy of KIA MOTORS AMERICA, INC.

CYLINDER HEAD ASSEMBLY

COMPONENTS

| Helpmelearn | | |
|-----------------------|---------|--|
| June-06-08 8:54:30 AM | Page 72 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona




Fig. 73: Exploded View Of Cylinder Head Assemblies Courtesy of KIA MOTORS AMERICA, INC.

DISASSEMBLY

Arrange removal parts according to cylinder numbers, intake and exhaust valves.

REMOVING CYLINDER HEAD BOLT

Remove the cylinder head bolts using the hexagonal wrench.

| Helpmelearn | | |
|-----------------------|---------|--|
| June-06-08 8:54:30 AM | Page 73 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona

REMOVING RETAINING LOCK

1. Compress the valve spring using Service Tool (09222-28000, 09222-28100).




Fig. 74: Compressing Valve Springs Courtesy of KIA MOTORS AMERICA, INC.

2. Remove the retainer lock.

REMOVING VALVE STEM SEAL

Do not reuse the valve stem seal.

| Helpmelearn | | | |
|-----------------------|---------|--|--|
| June-06-08 8:54:30 AM | Page 74 | © 2005 Mitchell Repair Information Company, LLC. | |

2002 ENGINES 3.5L V6 - Sedona




Fig. 75: Removing Valve Stem Seals
Courtesy of KIA MOTORS AMERICA, INC.

INSPECTION & SERVICING

CYLINDER HEAD (Bare)

- 1. Remove scale, sealing compound and carbon deposits completely. After cleaning oil passages, apply compressed air to make certain that the passages are not clogged.
- 2. Visually check the cylinder head for cracks, damage or water leakage.
- 3. Check the cylinder head gasket surface for flatness with a straight edge and feeler as shown in illustration


Flatness of cylinder head gasket:

Standard dimension: 0.03mm (0.0012 in) or lower

Service limit: 0.2mm (0.0079 in)

| Helpmelearn | | | |
|-----------------------|---------|--|--|
| June-06-08 8:54:30 AM | Page 75 | © 2005 Mitchell Repair Information Company, LLC. | |

2002 ENGINES 3.5L V6 - Sedona



G00320664

Fig. 76: Measuring Cylinder Head Flatness Courtesy of KIA MOTORS AMERICA, INC.

VALVES

1. Clean the valve with wire brush.

| Helpmelearn | | | |
|-----------------------|---------|--|--|
| June-06-08 8:54:30 AM | Page 76 | © 2005 Mitchell Repair Information Company, LLC. | |

2002 ENGINES 3.5L V6 - Sedona




Fig. 77: Illustrating Cleaning Valves
Courtesy of KIA MOTORS AMERICA, INC.

2. Inspect wear and damage of each valve. Check for bending at the valve head and stem if there is wear, replace the valve. If margin is smaller than service standard, replace the valve.

VALVE MEASUREMENTS

| Application | Margin Standard In. (mm) | Margin Limit In. (mm) |
|-------------|--------------------------|-----------------------|
| Intake | 0.039 (1.0) | 0.02 (0.5) |
| Exhaust | 0.059 (1.5) | 0.039 (1.0) |

| Helpmelearn | | |
|-----------------------|---------|--|
| June-06-08 8:54:30 AM | Page 77 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona




Fig. 78: Illustrating Valve Margin Courtesy of KIA MOTORS AMERICA, INC.

| Helpmelearn | | |
|-----------------------|---------|--|
| June-06-08 8:54:30 AM | Page 78 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona

VALVE SPRINGS

- 1. Check free height of each valve spring and replace if necessary.
- 2. Using a square, test squareness of each valve spring. If spring is excessively out of square, replace it.

VALVE SPRING HEIGHT MEASUREMENTS

| Application | Margin Standard In. (mm) | Margin Limit In. (mm) |
|---------------------|--------------------------|-----------------------|
| Height With No Load | 1.8268 (46.4) | 1.7874 (45.4) |

VALVE SPRING RECTANGULARITY MEASUREMENTS

| Application | Standard | Margin Limit |
|-----------------------------|---------------------|--------------|
| Deviation Of Rectangularity | Less Than 2 Degrees | 4 Degrees |




Fig. 79: Measuring Valve Spring Values

| Helpmelearn | | | |
|-----------------------|---------|--|--|
| June-06-08 8:54:30 AM | Page 79 | © 2005 Mitchell Repair Information Company, LLC. | |

2002 ENGINES 3.5L V6 - Sedona

Courtesy of KIA MOTORS AMERICA, INC.

VALVE GUIDE

Check the valve stem-to-guide clearance. If the clearance exceeds the service limit, replace the valve guide with a new oversize guide.

VALVE GUIDE MEASUREMENTS

| Application | Margin Standard In. (mm) | Service Limit In. (mm) |
|-------------|---------------------------|------------------------|
| Intake | 0.0009-0.00020 (.0205) | 0.0039 (0.1) |
| Exhaust | 0.002-0.0033 (0.05-0.085) | 0.0059 (0.15) |




Fig. 80: Measuring Valve Guide Clearance Courtesy of KIA MOTORS AMERICA, INC.

VALVE SEAT INSERT

Inspect for any trace of overheating and the contact state of valve face. If necessary, repair or replace it. When repairing, inspect for wear in the valve guide. If the guide is worn, replace it and adjust the seat ring. Adjust the valve seat with grinder or cutter making valve seat contact width from the center of valve face to within the specified value. When adjusting the exhaust valve seat, use the valve seat cutter or pilot. After adjustment, lapping process can be made by using applying compound on the valve and valve seat.

| Helpmelearn | | | |
|-----------------------|---------|--|--|
| June-06-08 8:54:30 AM | Page 80 | © 2005 Mitchell Repair Information Company, LLC. | |

2002 ENGINES 3.5L V6 - Sedona






Fig. 81: Grinding Valve Seat Courtesy of KIA MOTORS AMERICA, INC.

| Helpmelearn | | |
|-----------------------|---------|--|
| June-06-08 8:54:30 AM | Page 81 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona





G00320672

Fig. 82: Valve Seat Angle Chart Courtesy of KIA MOTORS AMERICA, INC.

VALVE SEAT REPLACEMENT PROCEDURE

1. If the valve seat insert is excessively worn, cut out the insert wall using valve seat cover at normal temperature. See figure "A" in figure 83.

| Helpmelearn | | |
|-----------------------|---------|--|
| June-06-08 8:54:30 AM | Page 82 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona




Fig. 83: Insert Wall Removal Diagram Courtesy of KIA MOTORS AMERICA, INC.

- 2. After removing the seat insert, match the seat insert bore using a reamer or cutter to the indicated size in the table below.
- 3. Heat the cylinder head up to 250°C and press in an oversize seat insert. At this time, the temperature of oversize seat insert must be the same as the room temperature. When new valve seat is installed, adjust the valve seat face. For valve seat specifications, see chart in figure 84.

| Description | Size (mm) | Size mark | Seat insert height H (mm) | Cylinder head i.D (mm) |
|---------------|--------------|--------------|----------------------------------|-----------------------------------|
| Intake valve | 0.3 O.S. | 30 | 7.5 - 7.7mm (0.2953 - 0.3031 in) | 36.30 - 36.325 (1.429 - 1.430 in) |
| Seat insert | 0.6 O.S. | 60 | 7.8 - 8.0mm (0.3071 - 0.3150 in) | 36.60 - 36.625 (1.441 - 1.442 in) |
| Exhaust valve | 0.3 O.S. | 30 | 8.0 - 8.2mm (0.3150 - 0.3228 in) | 33.30 - 33.325 (1.311 - 1.312 in) |
| Seat insert | 0.6 O.S. | 60 | 8.3 - 8.5mm (0.3268 - 0.3346 in) | 33.60 - 33.625 (1.323 - 1.324 in) |

G00320674

Fig. 84: Valve Seat Specifications Chart Courtesy of KIA MOTORS AMERICA, INC.

VALVE GUIDE REPLACEMENT PROCEDURE

| Helpmelearn | | |
|-----------------------|---------|--|
| June-06-08 8:54:30 AM | Page 83 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona

As the valve guide is tightly pressed in, replace the valve guide using following procedure, using the valve guide installer or appropriate tools.

- 1. Using the push rod of the valve guide installer, push it out of initial position by pushing it to the cylinder block side.
- 2. Machine insert hole of the cylinder head valve guide to the size of oversize valve guide.
- 3. Press in the valve guide using the valve guide installer or appropriate tools. By using the valve guide installer, it can be pressed in the specified height.




Fig. 85: Illustrating Valve Guide Installation Tool Courtesy of KIA MOTORS AMERICA, INC.

4. Valve guide is to be installed from the upside of the cylinder head.

As length of the intake valve guide is different from that of the exhaust valve guide, be careful. (The lengths of guide for intake valve and exhaust valve are 45.5mm and 50.5mm respectively.)

After installing the valve guide, insert the new valve and check sliding state.

| Helpmelearn | | |
|-----------------------|---------|--|
| June-06-08 8:54:30 AM | Page 84 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona




Fig. 86: Measuring Valve Guide Length Courtesy of KIA MOTORS AMERICA, INC.

5. When the valve guide is replaced, inspect for valve contact state. If necessary, adjust the valve seat.

VALVE GUIDE INSERT OVERSIZES

| Helpmelearn | | |
|-----------------------|---------|--|
| June-06-08 8:54:31 AM | Page 85 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona

| Size (mm) | Size mark | Inner diameter of hole for guide insertion |
|-----------|-----------|--|
| 0.05 O.S. | 5 | 12.05-12.068 mm (0.474 - 0.475 in) |
| 0.25 O.S. | 25 | 12.25-12.268 mm (0.482-0.483 in) |
| 0.50 O.S. | 50 | 12.50-12.518 mm (0.492-0.493 in) |

G00320677

Fig. 87: Valve Guide Oversize Chart Courtesy of KIA MOTORS AMERICA, INC.

REASSEMBLY

VALVE STEM SEAL

- 1. Install the valve spring seat.
- 2. Install a new stem seal on valve guide using the special tool (09222-28200).

| Helpmelearn | | | |
|-----------------------|---------|--|--|
| June-06-08 8:54:31 AM | Page 86 | © 2005 Mitchell Repair Information Company, LLC. | |

2002 ENGINES 3.5L V6 - Sedona




Fig. 88: Identifying Valve Stem Seal Position Courtesy of KIA MOTORS AMERICA, INC.

CAUTION: Valve stem seal should never be reused. Incorrect seal installation can cause oil leakage through lower part of the valve guide. When the valve stem seal is removed due to missing of valve spring seat, the stem seal cannot be reused.

| Helpmelearn | | |
|-----------------------|---------|--|
| June-06-08 8:54:31 AM | Page 87 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona




Fig. 89: Installing Valve Stem Seal Courtesy of KIA MOTORS AMERICA, INC.

VALVE SPRING

Install the valve spring so that the end part with identification mark is paced at the end of the spring retainer.

| Helpmelearn | | |
|-----------------------|---------|--|
| June-06-08 8:54:31 AM | Page 88 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona




Fig. 90: Positioning Valve Spring Courtesy of KIA MOTORS AMERICA, INC.

RETAINER LOCK

Insert the retainer lock by pressing down the valve spring with special tool (09222-28000).

| Helpmelearn | | |
|-----------------------|---------|--|
| June-06-08 8:54:31 AM | Page 89 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona




Fig. 91: Installing Valve Retainer Lock Courtesy of KIA MOTORS AMERICA, INC.

INSTALLATION

CYLINDER HEAD GASKET

- 1. All mating faces for the gasket on the cylinder block and the cylinder head should be cleaned.
- 2. Install new cylinder head gasket on the cylinder head assembly. Do not smear the sealant on the gasket and only the new gasket must be used.

| Helpmelearn | | |
|-----------------------|---------|--|
| June-06-08 8:54:31 AM | Page 90 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona





Fig. 92: Illustrating Cylinder Head Gasket Courtesy of KIA MOTORS AMERICA, INC.

CYLINDER HEAD BOLT

1. Tighten the cylinder head bolts as shown in illustration below using the appropriate tool.

Tightening torque: 105-115 N.m (1050-1150 kg.cm, 75.9-83.2 lb.ft)

| Helpmelearn | | |
|-----------------------|---------|--|
| June-06-08 8:54:31 AM | Page 91 | © 2005 Mitchell Repair Information Company, LLC. |



G00320666


Fig. 93: Illustrating Cylinder Head Tightening Sequence Courtesy of KIA MOTORS AMERICA, INC.

LUBRICATION SYSTEM

COMPONENTS

| Helpmelearn | | | |
|-----------------------|---------|--|--|
| June-06-08 8:54:31 AM | Page 92 | © 2005 Mitchell Repair Information Company, LLC. | |

2002 ENGINES 3.5L V6 - Sedona



TORQUE: N·m (kg·cm, lb·ft)

G00320626


Fig. 94: Exploded View Of Oil Pump & Oil Pan Courtesy of KIA MOTORS AMERICA, INC.

DISASSEMBLY

1. Remove the oil pressure switch, using 24 mm deep socket.

| Helpmelearn | | | |
|-----------------------|---------|--|--|
| June-06-08 8:54:31 AM | Page 93 | © 2005 Mitchell Repair Information Company, LLC. | |

2002 ENGINES 3.5L V6 - Sedona



G00320627

Fig. 95: Removing Oil Pressure Switch Courtesy of KIA MOTORS AMERICA, INC.

NOTE: Since a sealant is used on the threaded area, be careful not to damage the oil pressure switch.

- 2. Remove the oil filter and the oil pan.
- 3. Remove the oil screen and gasket.
- 4. Remove the three bracket securing bolts and remove the oil filter bracket and gasket.
- 5. Remove the oil relief valve plug from the oil pump case.
- 6. Remove the oil pump case.

| INSPECTION |
|------------|
|------------|

| Helpmelearn | | |
|-----------------------|---------|--|
| June-06-08 8:54:31 AM | Page 94 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona

OIL PUMP

- 1. Visually check the parts of the oil pump case for cracks and damage.
- 2. Assemble the rotor on the oil pump and then check the clearance with a thickness gauge.

OIL PUMP CLEARANCE

| Application | Standard In. (mm) |
|----------------|-----------------------------|
| Body Clearance | 0.0039-0.0071 (0.100-0.181) |
| Side Clearance | 0.0016-0.0037 (0.040-0.095) |




Fig. 96: Illustrating Measuring Locations

| Helpmelearn | | | |
|-----------------------|---------|--|--|
| June-06-08 8:54:31 AM | Page 95 | © 2005 Mitchell Repair Information Company, LLC. | |

2002 ENGINES 3.5L V6 - Sedona

Courtesy of KIA MOTORS AMERICA, INC.




Fig. 97: Measuring Side & Body Clearance Courtesy of KIA MOTORS AMERICA, INC.

RELIEF PLUNGER AND SPRING

- 1. Check the relief plunger for smooth operation.
- 2. Check the relief spring for the deformed or broken condition.

OIL FILTER BRACKET

- 1. Make sure that there is no damage on the oil filter installation surface.
- 2. Check the oil filter bracket for oil leaks or cracks.

OIL PRESSURE SWITCH

1. Check the continuity by between terminal and body with an ohmmeter.

| Helpmelearn | | |
|-----------------------|---------|--|
| June-06-08 8:54:31 AM | Page 96 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona

If there is continuity, replace the oil pressure switch.




Fig. 98: Testing Oil Pressure Switch Continuity Courtesy of KIA MOTORS AMERICA, INC.

2. Check the continuity between the terminal and the body when the fine wedge is pushed. If there is continuity even when the fine wedge is pushed, replace it.

| Helpmelearn | | |
|-----------------------|---------|--|
| June-06-08 8:54:31 AM | Page 97 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona




Fig. 99: Testing Oil Pressure Switch Continuity When Activated Courtesy of KIA MOTORS AMERICA, INC.

3. Or, if there is no continuity when a 50kPa (0.5 kg/cm², 7psi) vacuum is applied through the oil hole, the switch is operating properly. Check that air doesn't leak. If air leaks, the diaphragm is broken, replace it.

REASSEMBLY

1. Install the oil pump case with the gasket.

Tightening torque:

Oil pump case bolt: 12-15 N.m (120-150 kg.cm, 8.85-11.06 lb.ft)

| of pump tast contract to the (120 feeting) | | |
|--|---------|--|
| Helpmelearn | | |
| June-06-08 8:54:31 AM | Page 98 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona

Oil pump cover screw: 8-12 N.m (80-120 kg.cm, 5.91-8.85 lb.ft)




Fig. 100: Positioning Oil Pump Case & Gasket Courtesy of KIA MOTORS AMERICA, INC.

2. Install the oil seal in the oil pump case, using special tool (09214-33000).

| Helpmelearn | | |
|-----------------------|---------|--|
| June-06-08 8:54:31 AM | Page 99 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona




Fig. 101: Installing Oil Pump Seal Courtesy of KIA MOTORS AMERICA, INC.

3. Install the relief plunger and spring, and tighten the oil relief valve plug to the specified torque.

Tightening torque:

Oil relief valve plug: 40-50 N.m (400-500 kg.cm, 29.5-36.88 lb.ft)

| Helpmelearn | | |
|-----------------------|----------|--|
| June-06-08 8:54:31 AM | Page 100 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona




Fig. 102: Installing Relief Plunger & Spring Courtesy of KIA MOTORS AMERICA, INC.

4. Install the oil screen with a new gasket.

| Helpmelearn | | | |
|-----------------------|----------|--|--|
| June-06-08 8:54:31 AM | Page 101 | © 2005 Mitchell Repair Information Company, LLC. | |

2002 ENGINES 3.5L V6 - Sedona

Tightening torque

Oil screen bolt: 15-22 N.m (150-220 kg.cm, 11.06-16.23 lb.ft)

- 5. Clean the gasket surfaces of the cylinder block and the oil pan.
- 6. Apply sealant into the groove of the oil pan flange.

NOTE: Make the first cut from the end of the nozzle furnished with the sealant approx. 4 mm. After application of the sealant, do not exceed 15 minutes before installing the oil pan.

7. Install the upper oil pan and tighten the bolts to the specified torque. Tighten the oil pan bolts as shown in figure.

Tightening torque

Upper oil pan bolt No.1-14: 9.8-11.8 N.m (100-120 kg.cm, 7.2-8.7 lb.ft) N.m No.15-16: 5-7 (50-70 kg.cm, 3.68-5.16 lb.ft)

Upper oil pan and transaxle mounting bolt (4EA): 30-42 N.m (300-420 kg.cm, 22.13-30.98 lb.ft)




Fig. 103: Upper Oil Pan Bolt Tightening Sequence

| Helpmelearn | | |
|-----------------------|----------|--|
| June-06-08 8:54:31 AM | Page 102 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona

Courtesy of KIA MOTORS AMERICA, INC.

8. Install the lower oil pan and tighten the bolts to specified torque.

Tightening torque:

Lower oil pan bolt: 9.8-11.8 N.m (100-120 kg.cm, 7.2-8.7 lb.ft)




Fig. 104: Lower Oil Pan Tightening Sequence Courtesy of KIA MOTORS AMERICA, INC.

9. Using 24 mm deep socket, install the oil pressure switch after applying sealant to the threaded area.


| Helpmelearn | | | |
|-----------------------|----------|--|--|
| June-06-08 8:54:31 AM | Page 103 | © 2005 Mitchell Repair Information Company, LLC. | |

2002 ENGINES 3.5L V6 - Sedona

Sealant: Threebond 1104 or equivalent.

NOTE: Do not tighten the oil pressure switch to the excessive torque.

Oil pressure switch tightening torque: 8-12 N.m (80-120 kg.cm, 5.91-8.85 lb.ft)



G00320637

Fig. 105: Tightening Oil Pressure Switch Courtesy of KIA MOTORS AMERICA, INC.


MAIN MOVING SYSTEM

CONNECTING ROD & PISTON ASSEMBLY

| Helpmelearn | | |
|-----------------------|----------|--|
| June-06-08 8:54:31 AM | Page 104 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona

COMPONENTS



TORQUE: N·m (kg·cm, lb·ft)

G00320554

Fig. 106: Exploded View Of Connecting Rod & Piston Assembly Courtesy of KIA MOTORS AMERICA, INC.

DISASSEMBLY

CONNECTING ROD CAP

| Helpmelearn | | | |
|-----------------------|----------|--|--|
| June-06-08 8:54:31 AM | Page 105 | © 2005 Mitchell Repair Information Company, LLC. | |


2002 ENGINES 3.5L V6 - Sedona

CAUTION: Keep the bearings in order with their corresponding connecting rods (according to cylinder numbers) for proper reassembly.

- 1. Remove the connecting rod cap bolts, then remove the caps and the big end lower bearing mark for reassembly.
- 2. Push each piston connecting rod assembly toward the top of the cylinder.

| Helpmelearn | | |
|-----------------------|----------|--|
| June-06-08 8:54:31 AM | Page 106 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona



G00320555


| Helpmelearn | | |
|-----------------------|----------|--|
| June-06-08 8:54:31 AM | Page 107 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona

Fig. 107: Marking Connecting Rod Assemblies Courtesy of KIA MOTORS AMERICA, INC.

PISTON PIN REMOVAL & INSTALLATION

1. Use the appropriate tool to disassemble piston and connecting rod.



<u>Fig. 108: Illustrating Removal & Installation Tools</u> Courtesy of KIA MOTORS AMERICA, INC.

- 2. Place the proper insert tool between the connecting rod and piston.
- 3. Insert the proper removing tool through the hole.

CAUTION: After removing the piston rod pin assembly, put in the center of the arbor.

| Helpmelearn | | |
|-----------------------|----------|--|
| June-06-08 8:54:31 AM | Page 108 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona




Fig. 109: Piston Pin Removal Fixture Courtesy of KIA MOTORS AMERICA, INC.

- 4. Press the piston pin out of the connecting rod.
- 5. Install proper pin guide through piston into connecting rod. Hand tap pin guide into piston for proper retention. Install piston pin into the other side of the piston.

| Helpmelearn | | | |
|-----------------------|----------|--|--|
| June-06-08 8:54:31 AM | Page 109 | © 2005 Mitchell Repair Information Company, LLC. | |

2002 ENGINES 3.5L V6 - Sedona





Fig. 110: Piston Pin Installation Fixture Courtesy of KIA MOTORS AMERICA, INC.

CAUTION: The pin guide centers on the connecting rod in the piston. When the piston, connecting rod, piston pin and pin guide assembly are positioned on the fork tool, the guide pin will also center on the tool assembly. If a pin guide that is too small is used, the piston assembly will not be located at the center of the tool and may cause the fork and/or the insert of the tool to be damaged.

6. Install piston assembly on the fork assembly of tool. Tool will support connecting rod at the piston pin. Be sure the piston assembly is slid onto the fork until the pin guide contacts the fork insert.

| Helpmelearn | | |
|-----------------------|----------|--|
| June-06-08 8:54:31 AM | Page 110 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona



G00368069

Fig. 111: Illustrating Fixture Set-Up Courtesy of KIA MOTORS AMERICA, INC.

- 7. Adjust the installing arbor to the proper length by turning the numbered sleeve on the lettered shaft until the specified alphanumeric is obtained.
- 8. Insert the installing tool through the hole in the arch of the tool. Press the piston pin into the connecting rod until the sleeve in the installing arbor contacts the top of the tool arch. The pin guide will fall out of

| Helpmelearn | | |
|-----------------------|----------|--|
| June-06-08 8:54:31 AM | Page 111 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona

the connecting rod as the piston pin is pressed in.

CAUTION: Do not exceed 5000 pounds of force when stopping the installation arbor sleeve against the arch.

INSPECTION

PISTONS AND PISTON PINS


- 1. Check each piston for scuffing, scoring, wear and other defects. Replace any piston that is defective.
- 2. Check each piston ring for breakage, damage and abnormal wear. Replace the defective rings. When the piston requires replacement, its rings should also be replaced.
- 3. Check that the piston pin fits in the piston pin hole. Replace any piston and pin assembly that is defective. The piston pin must be pressed smoothly by hand into the pin hole (at room temperature).

PISTON RINGS

- 1. Measure the piston ring side clearance. If the measured value exceeds the service limit, insert a new ring in the ring groove the measure the side clearance. If the clearance still exceeds the service limit, replace the piston and rings together. If it is less than the service limit, replace only the piston rings.
 - Piston ring side clearance ring No. 1: 0.04-0.08 mm (0.0016-0.0031 in.) Limit 0.01 mm (0.0039 in.)
 - Piston ring side clearance ring No. 2: 0.02-0.06 mm (0.0008-0.0024 in.) Limit 0.01 mm (0.0039 in.)

| Helpmelearn | | |
|-----------------------|----------|--|
| June-06-08 8:54:31 AM | Page 112 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona



G00320557

Fig. 112: Exploded View Of Piston Rings Courtesy of KIA MOTORS AMERICA, INC.

| Helpmelearn | | |
|-----------------------|----------|--|
| June-06-08 8:54:31 AM | Page 113 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona

- 2. To measure the piston ring end gap, insert a piston ring into the cylinder bore. Position the ring at right angles to the cylinder wall by gently pressing it down with a piston. Measure the gap with a feeler gauge. If the gap exceeds the service limit, replace the piston ring.
 - Piston ring end gap No. 1: 0.2-0.3 mm (0.0079-0.0118 in.). Limit 0.8 mm (0.031 in.)
 - Piston ring end gap No. 2: 0.45-0.60 mm (0.0177-0.236 in.) Limit 0.8 mm (0.031 in.)
 - Oil ring side rail: 0.2-0.7 mm (0.0079-0.0276) Limit 1.0 mm (0.039 in.)
 - When replacing the ring without correcting the cylinder bore, check the gap with the ring situated at the lower part of cylinder that is less worn.
- 3. When replacing the ring without correcting the cylinder bore, check the gap with the ring positioned at the lower part of the cylinder that is the less worn. When replacing a ring, be sure to the use a ring of the same size.

PISTON RING MARK & LIMIT

| Mark | Limit Standard In. (mm) |
|--------|-------------------------|
| OS 25 | 0.25 mm |
| OS 50 | 0.50 mm |
| OS 75 | 0.75 mm |
| OS 100 | 0.100 mm |


NOTE: The mark can be found on the upper side of the ring next to the end.

CONNECTING RODS

- 1. When the connecting rod cap is installed, make sure that the cylinder numbers, marked on rod end cap at disassembly, match. When a new connecting rod is installed, make sure that the notches holding the bearing in place are on the same side.
- 2. Replace the connecting rod if it is damaged at either end of the thrust faces. If it has a wear, or if the surface of the inside diameter of the small end is severely rough, replace the rod.

| Helpmelearn | | |
|-----------------------|----------|--|
| June-06-08 8:54:31 AM | Page 114 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona



G00320558

Fig. 113: Positioning Connecting Rod Bearing Courtesy of KIA MOTORS AMERICA, INC.

REASSEMBLY

1. Install the expander.

| Helpmelearn | | | |
|-----------------------|----------|--|--|
| June-06-08 8:54:31 AM | Page 115 | © 2005 Mitchell Repair Information Company, LLC. | |

2002 ENGINES 3.5L V6 - Sedona




Fig. 114: Positioning Oil Ring Courtesy of KIA MOTORS AMERICA, INC.

2. Install the upper side rail. To install the side rail, first put one end of the side rail between the piston ring groove and spacer, hold it firmly, and press down with finger on the portion to be inserted into the groove. See **Fig. 115**.

CAUTION: Do not use a piston ring expander when installing the side rail.

3. Install the lower side rail by the same procedure described above.

| Helpmelearn | | |
|-----------------------|----------|--|
| June-06-08 8:54:31 AM | Page 116 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona




Fig. 115: Installing Oil Ring Side Rail Courtesy of KIA MOTORS AMERICA, INC.

- 4. Apply engine oil around the piston and piston grooves.
- 5. Using a piston ring expander, install the No. 2 piston ring.
- 6. Install the No. 1 piston ring.




Fig. 116: Installing Piston Rings Courtesy of KIA MOTORS AMERICA, INC.

| Helpmelearn | | |
|-----------------------|----------|--|
| June-06-08 8:54:32 AM | Page 117 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona

7. Position each piston ring end gap as far away from its neighboring gaps as possible. Make sure that the gaps are not positioned in the thrust and pin directions.





Fig. 117: Positioning Piston Rings Courtesy of KIA MOTORS AMERICA, INC.

- 8. Hold the piston rings firmly with a piston ring compressor as they are inserted into cylinder.
- 9. Install the upper connecting rod bearings into the connecting rod.
- 10. Install the lower connecting rod bearings into the connecting rod bearing caps.
- 11. Make sure that the front mark of the piston and the front mark (identification mark) of the connecting rod are directed toward the front of the engine.
- 12. When the connecting rod cap is installed, make sure that any cylinder numbers placed on the rod and cap at disassembly match.
- 13. When a new connecting rod is installed, make sure that the notches for holding the bearing in place are on the same side.

| Helpmelearn | | | |
|-----------------------|----------|--|--|
| June-06-08 8:54:32 AM | Page 118 | © 2005 Mitchell Repair Information Company, LLC. | |

2002 ENGINES 3.5L V6 - Sedona



G00320564

Fig. 118: Positioning Connecting Rod Bearing Cap Courtesy of KIA MOTORS AMERICA, INC.

- 14. When assembling, bolts should be fastened using the following technique.
 - a. Apply oil to the threads and matching areas.
 - b. Tighten the connecting rod bolt.

Connecting rod bolt, tightening torque: 35 N.m + 92° (350 kg.cm + 92°, 26 lb.ft + 92°)

| Helpmelearn | | |
|-----------------------|----------|--|
| June-06-08 8:54:32 AM | Page 119 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona

CAUTION: After removing the connecting rod bolt, do not use it again. When using a new bolt, do not tighten the bolt more than 3 times.

- 15. Check the bearing clearance as follows:
 - a. Remove oil and dirt from the bearings and journals.
 - b. Cut plastigauge to the same length as the width of the bearing and place it in parallel with the journal, avoiding the oil holes.
 - c. Install the bearing and cap. Tighten to the specified torque. During this operation, do NOT turn the crankshaft.
 - d. Remove the cap, measure at the widest part by using the scale printed on the plastigauge package.

Connecting rod cap bearing clearance, standard value: 0.022-0.040 mm (0.0009-0.0016 in).

Limit: 0.1 mm (0.0039 in)




Fig. 119: Measuring Bearing Clearance Courtesy of KIA MOTORS AMERICA, INC.


| Helpmelearn | | |
|-----------------------|----------|--|
| June-06-08 8:54:32 AM | Page 120 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona

16. Check the connecting rod side clearance.

Connecting rod side clearance, standard: 0.10-0.25 mm (0.0039-0.0098 in.)

Limit: 0.4 mm (0.0157 in.)



G00320566


Fig. 120: Measuring Bearing Side Clearance Courtesy of KIA MOTORS AMERICA, INC.

CRANK SHAFT

COMPONENTS

| Helpmelearn | | |
|-----------------------|----------|--|
| June-06-08 8:54:32 AM | Page 121 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona



TORQUE: N·m (kg·cm, lb·ft)

G00320573

Fig. 121: Exploded View Of Crankshaft Components Courtesy of KIA MOTORS AMERICA, INC.

DISASSEMBLY

- 1. Remove the timing belt, cylinder head assembly, drive plate, transaxle mounting plate oil pan. See **TIMING SYSTEM**.
- 2. Remove the oil seal case and the rear oil seal.

| Helpmelearn | | |
|-----------------------|----------|--|
| June-06-08 8:54:32 AM | Page 122 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona

3. Remove the connecting rod caps.

NOTE: Mark the main bearing caps to reassemble in the original position and direction.

4. Remove the main bearing caps and remove the crankshaft.

Keep the bearings in order by cap number.

INSPECTION

CRANKSHAFT

1. Check the crankshaft journals and pins for damage, uneven wear and cracks. Also check the oil holes for restrictions.

Repair or replace any defective part.

2. Inspect for out-of-roundness and taper of the crankshaft journal and pin.

| Crankshaft journal O.D | Crankshaft pin O.D |
|------------------------|--------------------|
| 63.982-64.000mm | 54.982-55.000mm |
| (2.519-2.520in) | (2.164-2.165 in) |

G00320574

Fig. 122: Crankshaft Specification Courtesy of KIA MOTORS AMERICA, INC.

| Helpmelearn | | |
|-----------------------|----------|--|
| June-06-08 8:54:32 AM | Page 123 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona




Fig. 123: Measuring Crankshaft Journal Courtesy of KIA MOTORS AMERICA, INC.

MAIN BEARING AND CONNECTING ROD BEARING

Visually inspect each bearing for peeling, melt, seizure and improper contact. Replace any defective bearings.

OIL CLEARANCE MEASUREMENT

Check for oil clearance by measuring the outside diameter of the crankshaft journal and the inside diameter of the bearing. The clearance can be obtained by calculating the difference between the measured outside and inside diameter.

Standard value

Oil clearance

Crankshaft main bearing: 0.018 - 0.036 mm (0.0007 - 0.0014 in)

| Helpmelearn | | |
|-----------------------|----------|--|
| June-06-08 8:54:32 AM | Page 124 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona

Connecting rod bearing: 0.022 - 0.040 mm (0.0009 - 0.0016 in)




Fig. 124: Measuring Oil Clearance Courtesy of KIA MOTORS AMERICA, INC.

PLASTIGAUGE METHOD

Plastigauge may be used to measure the clearance.

- 1. Remove oil and grease and any other dirt from the bearings and journals.
- 2. Cut the plastigauge to the same length as the width of the bearing and place it in parallel with the journal, avoiding the oil holes.

| Helpmelearn | | |
|-----------------------|----------|--|
| June-06-08 8:54:32 AM | Page 125 | © 2005 Mitchell Repair Information Company, LLC. |




Fig. 125: Measuring Oil Clearance Using Plastigauge Courtesy of KIA MOTORS AMERICA, INC.

3. Install the crankshaft, bearings and caps and tighten them to the specified torques. During this operation, do not turn the crankshaft. Remove the caps. Measure the width of the widest part by using the scale printed on the gauge package.

If the clearance exceeds the repair limit, the bearing should be replaced or an undersize bearing should be used.

When installing a new crankshaft, be sure to use standard size bearings.

Should the standard clearance not be obtained even after bearing replacement, the journal and pin should be ground to undersize and a bearing of the corresponding undersize should be installed.

OIL SEAL

Check the front and rear oil seals for damage or worn surfaces. Replace any seal that is defective.

DRIVING PLATE

| Helpmelearn | | |
|-----------------------|----------|--|
| June-06-08 8:54:32 AM | Page 126 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona

Grooved

Replace the distorted, damaged, or cracked drive plate.

REASSEMBLY

MAIN BEARING

1. Install the grooved main bearing (upper bearing) on the cylinder block side.




Fig. 126: Identifying Main Bearings Courtesy of KIA MOTORS AMERICA, INC.

- 2. Install the grooveless main bearing (lower bearing) on the main bearing cap side.
- Install the crankshaft. Apply engine oil to the journal and pin.
- 4. Caps should be installed with the arrow mark directed toward the front of the engine. The cap number sequence must be correct.
- 5. Tighten all cap bolts to the specified torque according to the order as shown, see **Fig. 127**.

Main bearing cap bolt, tightening torque: 68.6-78.5 N.m (700-800 kg.cm, 50.6-57.9 lb.ft)

| Helpmelearn | | |
|-----------------------|----------|--|
| June-06-08 8:54:32 AM | Page 127 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona




Fig. 127: Crankshaft Bearing Cap Tightening Sequence Courtesy of KIA MOTORS AMERICA, INC.

- 6. Cap bolt should be tightened to specified torque in 4~5 steps before being tightened to the specified torque.
- 7. Make certain that the crankshaft turns freely and has the proper crankshaft end play.

Crankshaft end play, standard value: 0.050-0.250 mm (0.00197-0.0098 in)

Limit: 0.35mm (0.014 in)

| Helpmelearn | | | |
|-----------------------|----------|--|--|
| June-06-08 8:54:32 AM | Page 128 | © 2005 Mitchell Repair Information Company, LLC. | |

2002 ENGINES 3.5L V6 - Sedona




Fig. 128: Measuring Crankshaft End Play Courtesy of KIA MOTORS AMERICA, INC.

8. Assemble the rear oil seal to oil case using the special tool (09231-33000).

| Helpmelearn | | |
|-----------------------|----------|--|
| June-06-08 8:54:32 AM | Page 129 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona




Fig. 129: Positioning Rear Oil Seal Onto Special Tool Courtesy of KIA MOTORS AMERICA, INC.


9. Install the drive plate and the adapter plate.

Tightening torque

Drive bolt: 73 - 77 N.m (730 - 770 kg.cm, 53.85 - 56.80 lb.ft)

| Helpmelearn | | | |
|-----------------------|----------|--|--|
| June-06-08 8:54:32 AM | Page 130 | © 2005 Mitchell Repair Information Company, LLC. | |

2002 ENGINES 3.5L V6 - Sedona



G00320582


Fig. 130: Installing Drive & Adapter Plates Courtesy of KIA MOTORS AMERICA, INC.

ENGINE BLOCK

COMPONENTS

| Helpmelearn | | |
|-----------------------|----------|--|
| June-06-08 8:54:32 AM | Page 131 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona



TORQUE: N·m (kg·cm, lb·ft)

G00320524

Fig. 131: Identifying Cylinder Block Components Courtesy of KIA MOTORS AMERICA, INC.

DISASSEMBLY

Remove the timing belt, cylinder head assembly, drive plate, transaxle mounting plate, oil pan and the oil pump case.

INSPECTING CYLINDER BLOCK

1. Visually check the cylinder block for scores, rust and corrosion.

| Helpmelearn | | |
|-----------------------|----------|--|
| June-06-08 8:54:32 AM | Page 132 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona

Also check for cracks or any other defects using a proper tool. Repair or replace the block if defective.

- 2. Measure the cylinder bore with a cylinder gauge at the three levels indicated in the directions of A and B, see **Fig. 132**.
 - Level 1: No. 1 piston ring position with piston at TDC.
 - Level 2: Center of cylinder
 - Level 3: Bottom of cylinder




Fig. 132: Measuring Cylinder Bore Courtesy of KIA MOTORS AMERICA, INC.

3. If the cylinder bores show more than the specified out-of round or taper, or if the cylinder walls are badly scuffed or scored, the cylinder block should be rebored and honed. New oversize pistons and rings should be installed.

Standard value

| Helpmelearn | | |
|-----------------------|----------|--|
| June-06-08 8:54:32 AM | Page 133 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona

Cylinder bore: 93.00-93.03 mm (3.66-3.663 in)

Deviation of concentricity and taper of cylinder bore: 0.02 mm (0.00079 in) or less

4. If a ridge exists at the top of the cylinder, cut it way with a ridge reamer.

5. Oversize pistons are available in four sizes.

Oversize piston size.

0.25 O.S.: 0.25 mm (0.01 in)

0.50 O.S.: 0.50 mm (0.02 in)

0.75 O.S.: 0.75 mm (0.03 in.)

1.00 O.S.: 1.00 mm (0.039 in.)

6. To rebore the cylinder to oversize, keep the specified clearance between the oversize piston and the bore, and make sure that all pistons used are of the same oversize. When measuring the piston outside diameter measure the section of the thrust surface at 10 mm (0.39 in) above the bottom of the piston skirt.

Clearance between piston and cylinder wall: 0.03-0.05 mm (0.001-0.002 in)

7. Check the flatness of the upper surface. If the top surface exceeds limits, grind it to a minimum limit value or replace. (Measuring method is same as that of cylinder head flatness.)

| Helpmelearn | | |
|-----------------------|----------|--|
| June-06-08 8:54:32 AM | Page 134 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona




Fig. 133: Measuring Cylinder Block Flatness Courtesy of KIA MOTORS AMERICA, INC.

Standard value:

Flatness of the gasket mating surface: less than 0.05 mm (0.002 in)

Limit Flatness of the gasket mating surface: 0.1 mm (0.0039 in)

CAUTION: When the cylinder head is assembled, grinding less than 0.2 mm is permissible. Grind the gasket surface of the cylinder block less than 0.2 mm.

BORING CYLINDER

1. Oversize pistons used should be determined on the basis of the largest bore cylinder.

PISTON MARK & LIMIT

| | Mark | | Limit Standard In. (mm) |
|-------|---------------------|----------|--|
| Helpn | <u>I</u> nelearn | | |
| June- | 06-08 8:54:32 AM | Page 135 | © 2005 Mitchell Repair Information Company, LLC. |

| 2002 Kia Sedona EX | |
|-------------------------------|--|
| 2002 ENGINES 3.5L V6 - Sedona | |

| OS 25 | 0.25 mi |
|--------|----------|
| OS 50 | 0.50 mi |
| OS 75 | 0.75 mi |
| OS 100 | 0.100 mi |

NOTE: Size mark is stamped on top of the piston.

2. Measure the outside diameter of the piston to be used.




Fig. 134: Measuring Piston Diameter Courtesy of KIA MOTORS AMERICA, INC.

3. Based on the measured O.D., calculate the boring finish dimension.

Boring finish dimension = piston outer diameter $+ 0.02 \sim 0.04$ mm (The clearance between piston outer diameter and cylinder) - 0.01 mm (Honing margin)

4. Bore each of the cylinders to the calculated size.

CAUTION: To prevent distortion that may result from temperature rise during honing, bore the cylinder holes in the firing order sequence.

- 5. Hone the cylinders, finishing them to the proper dimension (piston outside diameter + gap with cylinder).
- 6. Check the clearance between the piston and cylinder.

| Helpmelearn | | |
|-----------------------|----------|--|
| June-06-08 8:54:32 AM | Page 136 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona

Standard value: 0.03-0.05 mm (0.0012 - 0.0020 in)

NOTE:

- All cylinders should be bored to the same oversize.
- Never bore only one cylinder to an oversize.

COOLING SYSTEM

GENERAL

INLET CONTROL




Fig. 135: Illustrating Coolant Inlet Flow Courtesy of KIA MOTORS AMERICA, INC.

FLOW CHART

| Helpmelearn | | | |
|-----------------------|----------|--|--|
| June-06-08 8:54:32 AM | Page 137 | © 2005 Mitchell Repair Information Company, LLC. | |

2002 ENGINES 3.5L V6 - Sedona




Fig. 136: Illustrating Coolant Flow Chart Courtesy of KIA MOTORS AMERICA, INC.

RADIATOR

COMPONENTS

| Helpmelearn | | | |
|-----------------------|----------|--|--|
| June-06-08 8:54:32 AM | Page 138 | © 2005 Mitchell Repair Information Company, LLC. | |

2002 ENGINES 3.5L V6 - Sedona




Fig. 137: Locating Radiator Components Courtesy of KIA MOTORS AMERICA, INC.

REMOVAL

- 1. Remove the air duct.
- 2. Remove the hood locker.
- 3. Disconnect the horn connector.
- 4. Remove the shroud upper member.
- 5. Disconnect the radiator fan motor connector and the condenser fan motor connector.
- 6. Remove the radiator fan and the condenser fan.
- 7. After marking on the radiator hose and clamp, disconnect the upper, lower hose and over flow hose.
- 8. Remove the radiator.

INSPECTION

| Helpmelearn | | | |
|-----------------------|----------|--|--|
| June-06-08 8:54:32 AM | Page 139 | © 2005 Mitchell Repair Information Company, LLC. | |

2002 ENGINES 3.5L V6 - Sedona


- 1. Check if there are foreign objects among radiator fins.
- 2. Inspect the radiator fins for damage, if necessary, straighten them up.
- 3. Inspect the radiator for corrosion, damage and rust.
- 4. Inspect the radiator for crack, damage and any weakened part.

INSTALLATION

- 1. Fill the radiator reservoir tank with new coolant.
- 2. Run the engine till coolant temperature increases to open thermostat valve, and then stop the engine.
- 3. Remove the radiator cap and fill the radiator with water up to the filler neck, and fill the reservoir tank up to the specified level.
- 4. Check if there are any leakage from radiator, hose and connecting part.

RADIATOR CAP

COMPONENTS



When the pressure goes up to the specified level. 93.2~122.6 kPa (0.95~1.25kg/cm², 13.5~17.8 psi)

When the pressure goes down to the specified level. -0.98~4.90 kPa (-0.01~0.05kg/cm², -0.14~0.71 psi)


Fig. 138: Illustrating Radiator Cap Components Courtesy of KIA MOTORS AMERICA, INC.

INSPECTION

1. Inspect the radiator cap for damage, crack and weakening.

| Helpmelearn | | | |
|-----------------------|----------|--|--|
| June-06-08 8:54:32 AM | Page 140 | © 2005 Mitchell Repair Information Company, LLC. | |

2002 ENGINES 3.5L V6 - Sedona



G00320615

Fig. 139: Inspecting Radiator Cap Courtesy of KIA MOTORS AMERICA, INC.

- 2. Connect the radiator cap tester to the radiator cap.
- 3. Apply the pressure to the tester untill the needle is fixed.

| Helpmelearn | | |
|-----------------------|----------|--|
| June-06-08 8:54:32 AM | Page 141 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona




Fig. 140: Testing Radiator Cap Courtesy of KIA MOTORS AMERICA, INC.

4. If the needle stays at the same position for 10 seconds, the radiator cap is in good condition.

RADIATOR FAN MOTOR

COMPONENTS

| Helpmelearn | | |
|-----------------------|----------|--|
| June-06-08 8:54:32 AM | Page 142 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona




Fig. 141: Exploded View Of Fan Motor Assembly Courtesy of KIA MOTORS AMERICA, INC.

REMOVAL


- 1. Remove the air duct.
- 2. Remove the hood locker.
- 3. Disconnect the horn connector.
- 4. Remove the shroud upper member.
- 5. Disconnect the radiator fan motor connector.
- 6. Remove the radiator fan.

INSPECTION

- 1. Radiator fan motor
 - a. Check if the radiator fan is rotating when the battery voltage is supplied to both terminals as shown in the figure.

| Helpmelearn | | |
|-----------------------|----------|--|
| June-06-08 8:54:32 AM | Page 143 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona



G00320613

Fig. 142: Testing Radiator Fan Motor Courtesy of KIA MOTORS AMERICA, INC.

b. Check if there is abnormal noise while motor is rotating.

INSTALLATION

1. Installation is done in the reverse order of disassembly procedure.

CAUTION:

- When assembling the shroud, be cautions not to touch the cooling fan.
- After installing, while the fan is operating, check if there is abnormal noise and vibration.

ENGINE WATER PUMP

COMPONENTS

| Helpmelearn | | | |
|-----------------------|----------|--|--|
| June-06-08 8:54:32 AM | Page 144 | © 2005 Mitchell Repair Information Company, LLC. | |

2002 ENGINES 3.5L V6 - Sedona




Fig. 143: Exploded View Of Water Pump Assembly Courtesy of KIA MOTORS AMERICA, INC.

INSTALLATION

- 1. Clean the gasket mating surface of the water pump body and cylinder block.
- 2. After installing new O-ring in the groove at front of the water pipe, soak it with water. At this time, do not soak it with oil or grease.
- 3. After installing a new water pump gasket and water pump assembly, tighten it to the specified torque, see **Fig. 144**.

Tightening torque:

- (A) 5EA:14.7-21.6 N.m (150-220 kg.cm, 10.8-15.9 lb.ft)
- (B) 1EA:32.4-49.0 N.m (330-500 kg.cm, 23.9-36.2 lb.ft)
- (C) 2EA:19.6-26.5 N.m (200-270 kg.cm, 14.5-19.5 lb.ft)

| Helpmelearn | | | |
|-----------------------|----------|--|--|
| June-06-08 8:54:32 AM | Page 145 | © 2005 Mitchell Repair Information Company, LLC. | |

2002 ENGINES 3.5L V6 - Sedona




Fig. 144: Water Pump Tightening Sequence Courtesy of KIA MOTORS AMERICA, INC.


- 4. Install the timing belt tensioner and timing belt. After adjusting the timing belt tension, install the timing belt cover.
- 5. After installing the water pump pulley and driving belt, adjust the belt tension.
- 6. Refill it with coolant.
- 7. Check for leakage by running the engine.

THERMOSTAT

| Helpmelearn | | | |
|-----------------------|----------|--|--|
| June-06-08 8:54:32 AM | Page 146 | © 2005 Mitchell Repair Information Company, LLC. | |

2002 ENGINES 3.5L V6 - Sedona

COMPONENTS



TORQUE: N-m(kg-cm, lb-ft)

G00320617

Fig. 145: Exploded View Of Thermostat Components Courtesy of KIA MOTORS AMERICA, INC.

REMOVAL

- 1. Drain the coolant to the bottom level of thermostat.
- 2. Remove the water outlet fitting.
- 3. Remove the thermostat.

INSPECTION

1. Heat the thermostat and check if the valve operates properly.

| Helpmelearn | | |
|-----------------------|----------|--|
| June-06-08 8:54:32 AM | Page 147 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona

2. Check to determine the temperature at which the value begins to open and is completely opened.

Valve opening temperature: 80.0-84.0°C (176-183.2°F)

The temperature when the valve is completely opened: 95°C (203°F)




Fig. 146: Testing Thermostat Courtesy of KIA MOTORS AMERICA, INC.

INSTALLATION

1. Align the arrangement mark of thermostat housing with the jiggle valve.

| Helpmelearn | | | |
|-----------------------|----------|--|--|
| June-06-08 8:54:33 AM | Page 148 | © 2005 Mitchell Repair Information Company, LLC. | |




Fig. 147: Positioning Thermostat Courtesy of KIA MOTORS AMERICA, INC.

| Helpmelearn | | | |
|-----------------------|----------|--|--|
| June-06-08 8:54:33 AM | Page 149 | © 2005 Mitchell Repair Information Company, LLC. | |

2002 ENGINES 3.5L V6 - Sedona

- 2. Check to ensure that the flange of the thermostat at is correctly seated in the socket of the thermost at housing. If the thermostat is installed in the wrong direction, the bottom of the thermostat will touch the rib inside the intake manifold, making it impossible to seat flange in position.
- 3. Install a new gasket and engine coolant outlet fitting.

Engine coolant outlet fitting bolt, tightening torque: 17-20 N.m (170-200 kg.m, (12.54-14.75 lb.ft)


4. Refill the coolant.

ENGINE WATER HOSE/PIPES

COMPONENTS

| Helpmelearn | | | |
|-----------------------|----------|--|--|
| June-06-08 8:54:33 AM | Page 150 | © 2005 Mitchell Repair Information Company, LLC. | |

2002 ENGINES 3.5L V6 - Sedona



TORQUE: N·m(kg·cm, lb·ft)

G00320602

Fig. 148: Exploded View Of Water Hoses Courtesy of KIA MOTORS AMERICA, INC.

REMOVAL

WATER TEMPERATURE GAUGE UNIT AND SENSOR

- 1. Drain the coolant to the bottom level of the gauge unit.
- 2. After disconnecting the battery ground cable, disconnect engine harness.
- 3. Remove the water temperature gauge unit and sensor.

| Helpmelearn | | |
|-----------------------|----------|--|
| June-06-08 8:54:33 AM | Page 151 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona




Fig. 149: Locating Water Temp Gauge Unit Courtesy of KIA MOTORS AMERICA, INC.

INSPECTION

ENGINE COOLANT HOSE/PIPES

Check for cracks, damage, or blockage on the water hose and pipe, and replace if necessary.

WATER TEMPERATURE GAUGE UNIT AND SENSOR

- 1. Water temperature gauge unit
 - a. Heat up the water temperature gauge by immersing it in hot water.
 - b. Check if the resistance is within the specified range.

| Helpmelearn | | |
|-----------------------|----------|--|
| June-06-08 8:54:33 AM | Page 152 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona

| | 60°C (140°F) | 125Ω | |
|-----------|---------------|--------------------------------------|-----------|
| Specified | 85°C (185°F) | 8.4±5.8Ω | Coil type |
| Value | 110°C (230°F) | 24 ^{+2.2} _{-1.9} Ω | |
| | 125°C (257°F) | 15.2Ω | |

G00320604

Fig. 150: Temperature Gauge Resistance Chart Courtesy of KIA MOTORS AMERICA, INC.

- 2. Water temperature sensor
 - a. Immerse the sensor in hot water.
 - b. Check if the resistance is within the specified range.

| Charified value | 20°C(68°F) | 2.45±0.14kΩ |
|-----------------|-------------|--------------------|
| Specified value | 80°C(176°F) | 0.322 k Ω |

G00320605

Fig. 151: Temperature Sender Resistance Chart Courtesy of KIA MOTORS AMERICA, INC.

| Helpmelearn | | |
|-----------------------|----------|--|
| June-06-08 8:54:33 AM | Page 153 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona




Fig. 152: Testing Sending Unit Courtesy of KIA MOTORS AMERICA, INC.

INSTALLATION


ENGINE COOLANT HOSE/PIPES

After inserting O-ring into a groove at the lower part of water inlet pipe, soak O-ring in water and insert it into the water inlet pipe.

CAUTION:

- Be careful not to smear oil or grease on the water pipe O-ring.
- Pay attention not to let a foreign object get into the connecting part of the water pipe.
- Insert the water pipe up to its end part.

| Helpmelearn | | | |
|-----------------------|----------|--|--|
| June-06-08 8:54:33 AM | Page 154 | © 2005 Mitchell Repair Information Company, LLC. | |



G00320607

Fig. 153: Positioning Water Pipe O-Ring

| Helpmelearn | | |
|-----------------------|----------|--|
| June-06-08 8:54:33 AM | Page 155 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona

Courtesy of KIA MOTORS AMERICA, INC.

WATER TEMPERATURE GAUGE UNIT AND SENSOR

1. Apply the sealant on thread and then tighten it to the specified torque.

| Description | Recommended sealant | Tightening torque (N · m(kg · cm, lb · ft)) |
|--------------------------------|----------------------------|---|
| Water temperature sensor | Loctite 962T or equivalent | 20-40 (200- 400, 14.5- 28.9) |

G00320608

Fig. 154: Sealant & Tightening Chart Courtesy of KIA MOTORS AMERICA, INC.

- 2. Connect the harness to water temperature gauge unit and cable.
- 3. Connect the battery ground cable.
- 4. Refill the coolant.

AIR CLEANER

COMPONENTS

| Helpmelearn | | |
|-----------------------|----------|--|
| June-06-08 8:54:33 AM | Page 156 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona





Fig. 155: Identifying Air Cleaner Components Courtesy of KIA MOTORS AMERICA, INC.

| Helpmelearn | | |
|-----------------------|----------|--|
| June-06-08 8:54:33 AM | Page 157 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona

REMOVAL

1. Disconnect the AFS connector.



G00320659

Fig. 156: Locating AFS Connector Courtesy of KIA MOTORS AMERICA, INC.

- 2. Pull out air duct which is connected to the air inlet hose and air cleaner.
- 3. Detach the air cleaner.

INSPECTION

- 1. Inspect the body, cover and packing of air cleaner for distortion, corrosion and damage.
- 2. Inspect the air duct for damage.
- 3. Inspect the air cleaner element for dirt, contamination and damage. If element is choked a little, blow air from inside of element to get rid of the dust or other foreign object. If it is contaminated too much, replace it. While replacing it, be cautious not to let foreign object get in.

| Helpmelearn | | |
|-----------------------|----------|--|
| June-06-08 8:54:33 AM | Page 158 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona




Fig. 157: Cleaning Air Cleaner Courtesy of KIA MOTORS AMERICA, INC.


- 4. Inspect the air cleaner housing for dirt, contamination and damage.
- 5. If the inside of air cleaner housing is contaminated, eliminates the contaminated material.

SURGE TANK & INTAKE MANIFOLD

COMPONENTS

| Helpmelearn | | |
|-----------------------|----------|--|
| June-06-08 8:54:33 AM | Page 159 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona



TORQUE: N·m (kg·cm, lb·ft)

G00320645


Fig. 158: Exploded View Of Surge Tank & Intake Manifold Courtesy of KIA MOTORS AMERICA, INC.

REMOVAL

- 1. Detach the P.C.V. hose and brake booster vacuum hose.
- 2. Disconnect the connecting part of vacuum hose.

| Helpmelearn | | |
|-----------------------|----------|--|
| June-06-08 8:54:33 AM | Page 160 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona




G00320646

Fig. 159: Disconnecting PCV Hose Courtesy of KIA MOTORS AMERICA, INC.

3. Remove the surge tank stay.

| Helpmelearn | | |
|-----------------------|----------|--|
| June-06-08 8:54:33 AM | Page 161 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona



G00320647

Fig. 160: Removing The Surge Tank Stay Courtesy of KIA MOTORS AMERICA, INC.

4. After reducing the pressure of fuel pipe line to prevent fuel overflow, disconnect the connecting part of the high pressure hose.

| Helpmelearn | | |
|-----------------------|----------|--|
| June-06-08 8:54:33 AM | Page 162 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona




Fig. 161: Disconnecting High Pressure Fuel Hose Courtesy of KIA MOTORS AMERICA, INC.

5. Remove the surge tank.

| Helpmelearn | | |
|-----------------------|----------|--|
| June-06-08 8:54:33 AM | Page 163 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona




Fig. 162: Removing The Surge Tank Courtesy of KIA MOTORS AMERICA, INC.

6. After removing the surge tank, remove the gasket.

| Helpmelearn | | |
|-----------------------|----------|--|
| June-06-08 8:54:33 AM | Page 164 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona





Fig. 163: Removing Surge Tank Gasket Courtesy of KIA MOTORS AMERICA, INC.

7. Disconnect the fuel injector harness connector.

| Helpmelearn | | |
|-----------------------|----------|--|
| June-06-08 8:54:33 AM | Page 165 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona



G00320651

Fig. 164: Disconnecting Fuel Injector Harness Connector Courtesy of KIA MOTORS AMERICA, INC.

8. Remove the delivery pipe with fuel injector and pressure regulator attached.

CAUTION: When removing the delivery pipe, be cautions not to drop the injectors.

| Helpmelearn | | |
|-----------------------|----------|--|
| June-06-08 8:54:33 AM | Page 166 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona




Fig. 165: Removing Fuel Delivery Pipe Courtesy of KIA MOTORS AMERICA, INC.

9. Disconnect the wiring harness connector which is connected to the water temperature gauge unit and water temperature sensor assembly.

| Helpmelearn | | |
|-----------------------|----------|--|
| June-06-08 8:54:33 AM | Page 167 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona




Fig. 166: Disconnecting Wiring Harness Courtesy of KIA MOTORS AMERICA, INC.

- 10. Remove the water outlet fitting and gasket.
- 11. Remove the thermostat.

INSPECTION


- 1. Surge tank
 - a. Inspect the surge tank for damage and crack, if necessary, replace it.
 - b. Check if coolant passage is blocked.
 - c. Inspect the mating surface for warpage using a straight edge or filler gauge.

Standard value: 0.15 mm (0.006 in)

Service limit: 0.2 mm (0.008 in)

| Helpmelearn | | |
|-----------------------|----------|--|
| June-06-08 8:54:33 AM | Page 168 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona



G00320654

Fig. 167: Measuring Surge Tank Flatness Courtesy of KIA MOTORS AMERICA, INC.

INSTALLATION

1. After replacing the intake manifold gasket, install the surge tank and tighten to the specified torque.

Tightening torque: 19.6-22.6 N.m (200-230 kg.cm, 14.5-16.6 lb.ft.)

| Helpmelearn | | | |
|-----------------------|----------|--|--|
| June-06-08 8:54:33 AM | Page 169 | © 2005 Mitchell Repair Information Company, LLC. | |

2002 ENGINES 3.5L V6 - Sedona




Fig. 168: Illustrating Intake Manifold Courtesy of KIA MOTORS AMERICA, INC.


2. Install the delivery pipe and injector assembly to the intake manifold.

CAUTION: Check the interference between the injector and injector hole in intake manifold.

3. Install the surge tank stay.

| Helpmelearn | | |
|-----------------------|----------|--|
| June-06-08 8:54:33 AM | Page 170 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona



G00320656

Fig. 169: Installing Surge Tank Stay Courtesy of KIA MOTORS AMERICA, INC.

- 4. Install the fuel injector connector and wiring harness.
- 5. Connect the high pressure fuel hose.
- 6. Connect the various vacuum hose.
- 7. Connect the PCV valve hose and brake booster hose.
- 8. Install the idle speed actuator.
- 9. Installation of thermostat
 - a. Install the water outlet fitting gasket which is attached to thermost at housing.

Align the arrangement mark on thermost at housing with jiggle valve.

- b. Apply the sealant on coolant temperature sensor and cooling water temperature gauge unit.
- 10. Install the air hose.
- 11. Install the accelerator cable.


| Helpmelearn | | | |
|-----------------------|----------|--|--|
| June-06-08 8:54:33 AM | Page 171 | © 2005 Mitchell Repair Information Company, LLC. | |

2002 ENGINES 3.5L V6 - Sedona

EXHAUST SYSTEM

EXHAUST MANIFOLD

COMPONENTS



TORQUE: N·m(kg·cm, lb·ft)

G00320638

Fig. 170: Exploded View Of Exhaust Manifold Courtesy of KIA MOTORS AMERICA, INC.

REMOVAL

1. Remove the heat protector.

| Helpmelearn | | | |
|-----------------------|----------|--|--|
| June-06-08 8:54:33 AM | Page 172 | © 2005 Mitchell Repair Information Company, LLC. | |

2002 ENGINES 3.5L V6 - Sedona





Fig. 171: Removing Heat Protector Courtesy of KIA MOTORS AMERICA, INC.

2. Remove the exhaust manifold.

| Helpmelearn | | |
|-----------------------|----------|--|
| June-06-08 8:54:33 AM | Page 173 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona



G00320640

Fig. 172: Removing Exhaust Manifold Courtesy of KIA MOTORS AMERICA, INC.

INSPECTION

1. Exhaust manifold

- a. Check for cracks, replace if necessary.
- b. Check the distortion in mating surface with a straight edge and filler gauge

| Description | Torsion (mm) |
|----------------|-----------------|
| Standard value | 0.15 (0.006 in) |
| Limit | 0.3 (0.012 in) |

G00320641

| Helpmelearn | | | |
|-----------------------|----------|--|--|
| June-06-08 8:54:33 AM | Page 174 | © 2005 Mitchell Repair Information Company, LLC. | |

2002 ENGINES 3.5L V6 - Sedona

Fig. 173: Exhaust Manifold Flatness Specifications Courtesy of KIA MOTORS AMERICA, INC.




Fig. 174: Measuring Exhaust Manifold Flatness Courtesy of KIA MOTORS AMERICA, INC.

2. Heat protector, gasket

Check for damages and cracks in all parts, replace if necessary.

INSTALLATION

1. After installing the gasket, install the exhaust manifold.

Tightening torque: 40-50 N.m (400-500 kg.cm, 28.9-36.2 lb.ft.)

| Helpmelearn | | |
|-----------------------|----------|--|
| June-06-08 8:54:33 AM | Page 175 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona





Fig. 175: Installing Exhaust Manifold Courtesy of KIA MOTORS AMERICA, INC.

CAUTION: Use only new exhaust manifold gaskets and nuts.

2. Install the heat protector.

| Helpmelearn | | |
|-----------------------|----------|--|
| June-06-08 8:54:33 AM | Page 176 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona



G00320644

Fig. 176: Installing Heat Protector Courtesy of KIA MOTORS AMERICA, INC.

MUFFLER

COMPONENTS

| Helpmelearn | | |
|-----------------------|----------|--|
| June-06-08 8:54:34 AM | Page 177 | © 2005 Mitchell Repair Information Company, LLC. |

2002 ENGINES 3.5L V6 - Sedona




Fig. 177: Identifying Muffler Components
Courtesy of KIA MOTORS AMERICA. INC.

| Courtesy of Hill Motors Hill Enternation | | | |
|--|----------|--|--|
| Helpmelearn | | | |
| June-06-08 8:54:34 AM | Page 178 | © 2005 Mitchell Repair Information Company, LLC. | |